



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref: CS3/SMO22004736/Kcy3m4-1

50 RAFFLES PLACE #03-03  
SINGAPORE LAND TOWERSINGAPORE 048623

Date: 12/08/2022

Code: SMO

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	GBH 226A	<b>Veh. Inspected</b>	SGV 1233P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2201730/RUC	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	RUTH	<b>Assign Date</b>	14/07/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA ACCORD (A)	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2007
<b>Chassis No.</b>	CL71300861	<b>Colour</b>	RED
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/45 R17	BRIDGESTONE	7 mm
<b>L/H Front Tyre</b>	225/45 R17	BRIDGESTONE	7 mm
<b>R/H Rear Tyre</b>	225/45 R17	BRIDGESTONE	7 mm
<b>L/H Rear Tyre</b>	225/45 R17	BRIDGESTONE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	18/05/2022	<b>Inspection Date</b>	20/05/2022
<b>Survey held at</b>	BLK 7 SIN MING INDUSTRIAL ESTATE SECTOR C		
<b>Repairer</b>	GUAN AUTO SERVICE		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**