

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 04/08/2022

User ID : PohSuan

Section A - Accident Details

Registration Number	SHD6313S
Case Reference Number	TAX/07/22/2025
Registration Date	1/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HUANG WENXIONG
Type of Accident	Head To Side
Accident Date and Time	10/7/2022 7:30 PM
Accident Reported Date and Time	12/7/2022 11:19 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115574
Special Instruction to ARC, if any	RIGHT SIDE PASSENGER DOOR DAMAGED (OUR TAXI) LEFT SIDE MIRROR COVER DROPPED DUE TO THE IMPACT
Prepared Date and Time	12/7/2022 1:10 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,028.00	\$500.00
Total Spray Cost	\$2,034.00	\$500.00
Total Spare Part Cost	\$8,244.58	\$2,318.78
Total Other Cost	\$776.00	(\$568.78)
TOTAL COST	\$13,082.58	\$2,750.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	5.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	18/07/2022 10:38 AM	18/07/2022 10:09 AM
Signature		
Remarks	Total number of repair days = 5 days. SUP = 0 day.	resurvey after repair photo

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/08/2022
 User ID : PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2207-0421	Invoice Number	
Quotation Date	28.07.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,690.00	\$500.00
TO REPAIR LH PORTION	\$338.00	\$0.00
Total Labour	\$2,028.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY FLOOR CORNER PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,034.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$668.78)
Total Other Costs	\$776.00	(\$568.78)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8794047440	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,283.90	0.00	\$0.00	Replace	Not Given
		87945-74010	COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given
		5215947913	COVER, RR BUMPER ASSY	0.00	\$423.90	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		5245347010	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given
		5246247030	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/08/2022

User ID : PohSuan

	52462470 20	PAD, RR BUMPER, RH & LH , 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given	X
	52462470 10	PAD, RR BUMPER, RH & LH , 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given	X
	81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
	67003472 10	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair	R
	68750201 22	HINGE ASSY, REAR DOOR , UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given	X
	68770520 31	HINGE ASSY, REAR DOOR , LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given	X
	85720471 50	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Not Given	X
	69803470 20	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$200.70	0.00	\$0.00	Replace	Not Given	X
	68630470 50	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given	X
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	25.00	\$618.60	Replace	Replace	✓
	65565470 10	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$33.70	0.00	\$0.00	Replace	Not Given	X
	65637470 60	LINER, REAR FENDER , RH	1.00	\$135.80	25.00	\$101.85	Replace	Replace	✓
	42611474 50	WHEEL, DISC	1.00	\$1,555.10	25.00	\$1,166.33	Replace	Replace	✓
	43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Check	X
	75850479 10	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$576.00	100.00	\$0.00	Replace	Repair	
Total				\$9,796.40		\$1,886.78			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		75850479 10	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$576.00	25.00	\$432.00	Replace	Replace	✓ SCR
Total					576.00		432.00			

2,318.78
 + 500.00
 + 600.00 L/S \$2,750/-
 3,418.78
 -20%
 2,735.02