



Case Details

Case Reference Number :

TAX/07/22/2023

Type of Repair : Accident Repair

Vehicle Registration Number :
SHB1281T

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18784-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd

Accident Date and Time : 11/07/2022 04:30 AM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	10.00	682.63	Replace	1	0	Repair	R
Standard	Main			FENDER ASM-FRT - LH	1	379.80	379.80	10.00	341.82	Replace	1	0	Repair	R
Standard	Main			DOOR ASM-FRT SI -L	1	2,338.76	2,338.76	10.00	2,104.88	Replace	1	2,104.88	Replace	bt ✓
Standard	Main			HINGE ASM-RR S/D UPR-L	1	46.90	46.90	10.00	42.21	Replace	0	0	Not Givr	Xm
Standard	Main			HINGE ASM-RR S/D LWR-L	1	47.22	47.22	10.00	42.50	Replace	0	0	Not Givr	Xm
Standard	Main			CHECK ASM-FRT S/D-L	1	21.01	21.01	10.00	18.91	Replace	0	0	Not Givr	Xm
Standard	Main			REGULATOR ASM-FRT S/D WDO-L	1	324.06	324.06	10.00	291.65	Replace	0	0	Not Givr	Xm
Standard	Main			MOTOR ASM-FRT S/D WDO REG-L	1	169.00	169.00	10.00	152.10	Replace	0	0	Not Givr	Xm
Standard	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	nm ✓
Standard	Main			DOOR ASM-RR SI -L	1	2,185.04	2,185.04	10.00	1,966.54	Replace	1	1,966.54	Replace	bt ✓
Standard	Main			HINGE ASM-RR S/D UPR-L	1	46.90	46.90	10.00	42.21	Replace	0	0	Not Givr	Xm
Standard	Main			HINGE ASM-RR S/D LWR-L	1	47.22	47.22	10.00	42.50	Replace	0	0	Not Givr	Xm
Standard	Main			CHECK ASM-RR S/D LH	1	21.01	21.01	10.00	18.91	Replace	0	0	Not Givr	Xm

6442.40

Total Spare Part Cost 9,323.36

Lump Sum Discount (%) 0.00

Final Spare Part Cost 9,323.36

Surveyor Total 4,153.02

Lump Sum Dis (%) 0

Final Sur Total 4,153.02

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			REGULATOR ASM-RR S/D WDO-L	1	265.30	265.30	10.00	238.77	Replace	0	0	Not Givr	Xan
Standard	Main			MIRROR ASM-O/S RR VIEW - LH	1	478.40	478.40	10.00	430.56	Replace	1	0	Repair	R
Standard	Main			PANEL-BODY SI OTR-L	1	1,747.82	1,747.82	10.00	1,573.04	Replace	0	0	Not Givr	Xan
Standard	Main			PANEL-BODY SI OTR MID	1	323.23	323.23	10.00	290.91	Replace	0	0	Not Givr	Xan
Standard	Main			PANEL-BODY SI OTR FRT- LH	1	235.24	235.24	10.00	211.72	Replace	0	0	Not Givr	Xan
Standard	Main			STICKER ELECTRIC (LOGO	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓
Standard	Main			WHEEL	1	618.07	618.07	10.00	556.26	Replace	1	0	Repair	R
One Time Key In	Main			HANDLE-FRT S/D O/S - LH	1	36.92	36.92	10.00	33.23	Replace	1	0	Repair	R
One Time Key In	Main			COVER-FRT S/D LK CYL - LH	1	14.87	14.87	10.00	13.38	Replace	0	0	Not Givr	Xan
One Time Key In	Main			PLATE ASM-FRT S/D O/S HDL BKG - LH	1	32.86	32.86	10.00	29.57	Replace	0	0	Not Givr	Xan
One Time Key In	Main			WEATHERSTRIP ASM-FRT S/D (DR SI) - LH	1	63.96	63.96	10.00	57.56	Replace	0	0	Check	? Xan
One Time Key In	Main			WEATHERSTRIP ASM-FRT S/D (BODY SI)	1	66.56	66.56	10.00	59.90	Replace	0	0	Check	? Xan
						3904.83	Total Spare Part Cost	9,323.36			Surveyor Total	4,153.02		
							Lump Sum Discount (%)	0.00			Lump Sum Dis (%)	0		
							Final Spare Part Cost	9,323.36			Final Sur Total	4,153.02		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	3,600.00	700.00	
Total:			3,600.00	700.00	✓

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER LH	428.00	220.00	
2	Main	TO RESPRAY FRONT DOOR LH	428.00	220.00	
Total:			3,060.00	1,220.00	


No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY VIEW MIRROR	230.00	70.00	
4	Main	TO RESPRAY FRONT PILLAR LH	230.00	0.00 <i>XM</i>	
5	Main	TO RESRAY REAR DOOR LH	428.00	220.00	
6	Main	TO RESPRAY CENTRE PILLAR LH	230.00	0.00 <i>XM</i>	
7	Main	TO RESPRAY REAR FENDER LH	428.00	220.00	
8	Main	TO RESPRAY REAR BUMPER	428.00	220.00	
9	Main	TO RESPRAY RIM	230.00	50.00	
Total:			3,060.00	1,220.00 /	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0.00 <i>XM</i>	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0.00 <i>XM</i>	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	60.00	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00	
5	Main	TO TRANSFER DOOR MECHANISM	240.00	120.00	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0.00 <i>XM</i>	
7	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150.00	
8	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
Total:			1,340.00	540.00 /	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	9,323.36	4,153.02
Total Labour Cost	3,600.00	700.00
Total Spray Painting	3,060.00	1,220.00

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Other	1,340.00	540.00
Overall Total	17,323.36 18,347.23	6,613.02
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	6,613.02
Surveyor Approved Amount		6,613.02
No of Repair Days*	8	6
Remarks	-	resurvey before paint part by part
Surveyor Name		Rasul
Signature		
Survey Date	13/07/2022	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: