

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 13/07/2022

User ID : JeongCH

Section A - Accident Details

Registration Number	SG5431U
Case Reference Number	BUS/07/22/7006
Registration Date	2/14/2017
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	Phua Cheng Kee
Type of Accident	Head to Rear
Accident Date and Time	7/7/2022 10:01 AM
Accident Reported Date and Time	7/7/2022 10:45 AM
Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5431U - rear bumper dented SMJ1122J (TP) - INSURED WITH NTUC
Prepared Date and Time	7/13/2022 3:13 PM
Chassis Number	YV3S4P922HA181099
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$602.00	\$0.00
Total Spare Part Cost	\$671.34	\$0.00
Total Other Cost	\$480.00	\$0.00
TOTAL COST	\$671.34	\$0.00
Jump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	13/07/2022 3:22 PM	
Signature		<input type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/07/2022

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, If applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	795
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$602.00	432
Total Spray Painting & Panel Beating	\$602.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
ADVERTISEMENT STICKER	\$480.00	480
Total Other Costs	\$480.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
	Body	PLA-00798	NO PLATE RECESS PAN	1.00	\$321.15	10.00	\$289.03	Replace	6/1
	Body	B11-00081	REAR BUMPER PANEL	1.00	\$305.63	10.00	\$275.07	Replace	5/1
	Body	B11-00082	REAR BUMPER PANEL	1.00	\$305.63	10.00	\$275.07	Replace	5/1
			LIGHT,NUMBER PLATE FOR VOLVO B9TL BUS	2.00	\$123.93	10.00	\$223.07	Replace	CR
Total					\$1,056.34		\$1,062.24		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2546.17

L/S - 2036.93
= 2050

PARA
HP 90010068
3 days
L/S
13/07/22 @ 1720
Reg after repair