



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/07/2022

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1313B
Case Reference Number	BUS/07/22/7005
Registration Date	26/2/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Yeo Ching Heng Simon
Type of Accident	Head to Rear
Accident Date and Time	6/7/2022 2:24 PM
Accident Reported Date and Time	6/7/2022 7:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115609
Special Instruction to ARC,if any	SMB1313B - Rear left bumper cracked SLT640E (TP) - INSURED WITH NTUC
Prepared Date and Time	13/7/2022 2:10 PM
Chassis Number	WMAA22ZZ7D7001738
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,060.00
Total Spray Cost	\$786.00	\$616.00
Total Spare Part Cost	\$3,185.88	\$701.78
Total Other Cost	\$960.00	(\$335.20)
TOTAL COST	\$6,521.88	\$2,042.58
Lump Sum Total	\$0.00	\$2,050.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	Rasul
ARC / Surveyor Sign Off Date	13/07/2022 2:18 PM	13/07/2022 5:43 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/07/2022

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00				\$1,060.00		
Total Labour			\$1,590.00				\$1,060.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00				\$616.00		
Total Spray Painting & Panel Beating			\$786.00				\$616.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
ADVERTISEMENT STICKER			\$960.00				\$0.00		
Lump Sum Adjustment by Surveyor			\$0.00				(\$335.20)		
Total Other Costs			\$960.00				(\$335.20)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010064	Body	F01001-CW274	BUMPER:REAR,CENTR E,FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Replace	Repair
6010463	Body	S01001-CW006	FRAME,REAR BUMPER:FOR MAN A22 BUS	1.00	\$1,423.20	100.00	\$0.00	Replace	Repair
Total					\$4,266.70		\$877.23		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									