

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22006713/KPA3Q2**Date:** 28/02/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001461819
Claimant Vehicle No :	SLP9299U	Insured Vehicle No :	GBG2535A
Date of Loss:	09/07/2022	Nature of Claim:	TP
		Claim No:	202222005609

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP9299U		
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Engine No:	PE20879640
Reg. Date:	22/06/2017 (Man. Year: 2016)	Chassis No:	JM6GL1071H0114699
Colour:	Metallic Dark Blue	Odometer:	110175 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,515.36	14,058.88	1,456.48	9.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,760.00	1,090.00	38.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,365.36	15,818.88	2,546.48	13.87
Approved Total (Overridden) (\$\$)		12,650.00		
(\$\$)	18,365.36	12,650.00	5,715.36	31.12
+ GST 7.00/7.00% (\$\$)	1,285.58	885.50	400.08	31.12
Nett Amount (\$\$)	19,650.94	13,535.50	6,115.44	31.12
+ Car Rental (8.0 x S\$140.00/day) (\$\$)		1,120.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		14,662.95		

INSPECTION

Date of Assignment:	15/07/2022	Present Location:	Alan's United Auto Pte Ltd (HQ)
Date Inspected:	15/07/2022	Inspected At:	Alan's United Auto Pte Ltd (HQ)
			Blk 7 Sin Ming Industrial Estate, #01-76
			Singapore 575642
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP9299U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Bent	383.00 FL	*383.00 FL
2	1		*RH HEADLAMP	Cut	963.00 FL	*963.00 FL
3	1		*RH PILLAR A	Repair	1,076.00 FL	*- FL
4	1		*RH SIDE MIRROR ASSY	Dented / Jammed	794.00 FL	*794.00 FL
5	1		*FRONT RH DOOR	Bent	982.00 FL	*982.00 FL
6	2		*FRONT RH DOOR HINGE	Repair	152.00 FL	*- FL
7	1		*AIR BAG SENSOR	Necessary	187.00 FL	*187.00 FL
8	1		*AIR BAG CONTROL UNIT	Burst	1,548.00 FL	*1,548.00 FL
9	1		*ROOF LINING	Torn	1,340.00 FL	*1,340.00 FL
10	1		*DIRVER ROOF TOP AIR BAG (RH)	Burst	1,299.00 FL	*1,299.00 FL
11	1		*CENTRE PILLAR INNER UPPER GARNISH	Cracked	186.00 FL	*186.00 FL
12	1		*DRIVER SEAT AIR BAG	Burst	532.60 FL	*532.60 FL
13	1		*DRIVER SEAT REST ASSY	Torn	5,324.00 FL	*5,014.00 FL
14	1		*DRIVER SAFTEY BELT	Jammed	999.60 FL	*999.60 FL
15	1		*FRONT RH ABSORBER	Bent	392.00 FL	*392.00 FL
16	1		*FRONT RH LOWER ARM	Bent	509.00 FL	*503.90 FL
17	1		*FRONT RH KNUCKLE ARM	Bent	415.00 FL	*415.00 FL
18	1		*FRONT RH KNUCKLE BEARING HUP	Necessary	637.00 FL	*597.00 FL
19	1		*FRONT RH SPORT RIM	Dented	1,340.00 FS	*1,150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,059.20	17,286.10
- List Item Discount on L Items 20.00/20.00% (S\$)	3,543.84	3,227.22
Total Parts (S\$)	15,515.36	14,058.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ROOF LINING,FRONT & REAR SEATS.TRIM BOARD & CARPET	New	300.00	200.00
2	TO DISMANTLE & LOWER FRONT UNDERCARRIAGE	New	250.00	200.00
3	TO CHECK & ADJUST WHEEL ALIGNMENT	New	80.00	60.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	1,000.00	600.00
5	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX & TO RENEW ABOVE PARTS	New	900.00	500.00
6	TO REMOVE & RENEW ROOF TOP AIR BAG,SEAT AIR BAG,SAFTEY BELT,AIR BAG SENSOR,AIR BAG CONTROL UNIT,REWIRE ,DIAGNOS,PROGRAMME & RESET AIR BAG SYSTEM	New	320.00	200.00
Gross Labour Cost (S\$)			2,850.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >