

ASS. REC. BY:

REF:

A15 / 22 00 6713/ke

ASSIGNMENT

SEP 92994

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 7616

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Reg:

06 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes

C.C.

1998

Colour

M. D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

110175

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6GL107114 0114699

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

9/7/22

D.O.I.

15/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt body & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/8 11:50 @ 12,6501 Car

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
FOYSAL MOHAMMAD BIN

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	022107
Policy No:		Date of Loss:	09/07/2022
Vehicle Reg. No.:	SLP9299U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIM YEU FONG		

Make/Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Vehicle Reg. Date:	22/06/2017
Vehicle Colour:	BLUE		
Engine No:	PE20879640	Chassis No:	JM6GL1071H0114699
Odometer:	0 KM		

Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7 6 days		

*Not Notified
11 Sep 812, 650hr
Presum After Paint*

Present Location:	ALAN'S UNITED AUTO PTE LTD (HQ)
-------------------	---------------------------------

COST OF CLAIMS

	Amount
Parts	15,515.36
Miscellaneous Items	0.00
Labour	2,850.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	18,365.36
+ GST 7.00% (\$)	1,285.58
Nett Amount (\$)	19,650.94

This claim is handled by: CHAN YEW SIAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2022)

Parts: 143 MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Alan's United Auto Pte Ltd/SLP9299U/14/07/2022 14:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT RH FENDER	20.00	0.00	<i>R</i> *383.00 FL	✓
2	1		*RH HEADLAMP	20.00	0.00	<i>W</i> *963.00 FL	✓
3	1		*RH PILLAR A	20.00	0.00	<i>R</i> *1,076.00 FL	X
4	1		*RH SIDE MIRROR ASSY	20.00	0.00	<i>Ref / Tm</i> *794.00 FL	✓
5	1		*FRONT RH DOOR	20.00	0.00	<i>R</i> *982.00 FL	✓
6	2		*FRONT RH DOOR HINGE	20.00	0.00	<i>R</i> *152.00 FL	X
7	1		*AIR BAG SENSOR	20.00	0.00	<i>Ref</i> *187.00 FL	✓
8	1		*AIR BAG CONTROL UNIT	20.00	0.00	<i>Ref</i> *1,548.00 FL	✓
9	1		*ROOF LINING	20.00	0.00	<i>Tm</i> *1,340.00 FL	✓
10	1		*DIRVER ROOF TOP AIR BAG (RH)	20.00	0.00	<i>Ref</i> *1,299.00 FL	✓
11	1		*CENTRE PILLAR INNER UPPER GARNISH	20.00	0.00	<i>Ref</i> *186.00 FL	✓
12	1		*DRIVER SEAT AIR BAG	20.00	0.00	<i>Ref</i> *532.60 FL	✓
13	1		*DRIVER SEAT REST ASSY	20.00	0.00	<i>Tm</i> *5,324.00 FL	✓
14	1		*DRIVER SAFTEY BELT	20.00	0.00	<i>Tm</i> *999.60 FL	✓
15	1		*FRONT RH ABSORBER	20.00	0.00	<i>R</i> *392.00 FL	✓
16	1		*FRONT RH LOWER ARM	20.00	0.00	<i>R</i> *509.00 FL	✓
17	1		*FRONT RH KNUCKLE ARM	20.00	0.00	<i>R</i> *415.00 FL	✓
18	1		*FRONT RH KNUCKLE BEARING HUP	20.00	0.00	<i>Ref</i> *637.00 FL	✓
19	1		*FRONT RH SPORT RIM	0	0.00	<i>Ref</i> *1,340.00 FS	✓

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,059.20
- List Item Discount on L Items (S\$)	3,543.84
Total Parts (S\$)	15,515.36

Alan's United Auto Pte Ltd/SLP9299U/14/07/2022 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE ROOF LINING,FRONT & REAR SEATS.TRIM BOARD & CARPET	New	200 300.00
2	TO DISMANTLE & LOWER FRONT UNDERCARRIAGE	New	200 250.00
3	TO CHECK & ADJUST WHEEL ALIGNMENT	New	60 80.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	600 1,000.00
5	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX & TO RENEW ABOVE PARTS	New	300 900.00
6	TO REMOVE & RENEW ROOF TOP AIR BAG,SEAT AIR BAG,SAFTEY BELT,AIR BAG SENSOR,AIR BAG CONTROL UNIT,REWIRE ,DIAGNOS,PROGRAMME & RESET AIR BAG SYSTEM	New	200 320.00
Gross Labour Cost (\$\$)			2,850.00

Alan's United Auto Pte Ltd/SLP9299U/14/07/2022 14:35. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >