

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/HLA22006720/UQY3E2

**Date:** 08/08/2022

### REFERENCE

|                              |                      |                             |          |           |          |
|------------------------------|----------------------|-----------------------------|----------|-----------|----------|
| Handling Insurer:            | HL Assurance Pte Ltd | Policy No:                  | MP318754 |           |          |
| <b>Claimant Vehicle No :</b> | FBJ4587X             | <b>Insured Vehicle No :</b> | SNE32R   |           |          |
| Date of Loss:                | 07/07/2022           | Nature of Claim:            | TP       | Claim No: | MPC03549 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>FBJ4587X</b>                   | Engine No:  | 21CG039563        |
| Make & Model:               | YAMAHA FZ16, 153cc (M)            | Chassis No: | ME121C0GBD2039873 |
| Reg. Date:                  | 28/05/2014 (Man. Year: 2013)      | Odometer:   | 0 km              |
| Colour:                     | Blue                              |             |                   |
| Engine Capacity:            | 153 cc                            |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 110-70-17    | Rear Tyre Size:  | 140-70-17    |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | 0 mm         | Rear Right Side: | 0 mm         |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 6,950.40        | 2,553.90        | 4,396.50        | 63.26        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 940.00          | 300.00          | 640.00          | 68.09        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>7,890.40</b> | <b>2,853.90</b> | <b>5,036.50</b> | <b>63.83</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>2,200.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                 | <b>7,890.40</b> | <b>2,200.00</b> | <b>5,690.40</b> | <b>72.12</b> |

### INSPECTION

|                             |            |                                                                                                          |
|-----------------------------|------------|----------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 14/07/2022 |                                                                                                          |
| Date Inspected:             | 15/07/2022 | Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT)<br>1 KAKI BUKIT AVE 6 #02-62<br>Singapore 417883 |
| Estimated Period of Repair: | 4.0 days   |                                                                                                          |

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                         |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 08 Aug 2022)                                                                                                                                             |                                                         |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | YAMAHA FZ16 153cc (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                       |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for FBJ4587X)                                                                                                                                    |                                                         |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                         |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                         |

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *FRONT FENDER                       | Cut           | 105.00 FL  | *105.00 FL |
| 2   | 2   |          | *FORK INNER TUBES                   | Not Necessary | 480.00 FL  | *- FL      |
| 3   | 2   |          | *FORK OUTER TUBES                   | Not Necessary | 500.00 FL  | *- FL      |
| 4   | 1   |          | *FORK UNDER BRACKET                 | Not Necessary | 265.00 FL  | *- FL      |
| 5   | 1   |          | *FRONT RIM SHAFT                    | Not Necessary | 55.00 FL   | *- FL      |
| 6   | 1   |          | *FRONT RIM BEARING                  | Not Necessary | 45.00 FL   | *- FL      |
| 7   | 1   |          | *FRONT BRAKE DISC                   | Not Necessary | 185.00 FL  | *- FL      |
| 8   | 1   |          | *METER ASSY                         | Cut           | 620.00 FL  | *480.00 FL |
| 9   | 1   |          | *SIDE MIRROR O/S                    | Cut           | 140.00 FL  | *52.00 FL  |
| 10  | 1   |          | *FRONT SIGNAL O/S                   | Cut           | 140.00 FL  | *60.00 FL  |
| 11  | 1   |          | *HEADLAMP ASSY                      | Cut           | 580.00 FL  | *380.00 FL |
| 12  | 1   |          | *LAMPSTAY                           | Not Necessary | 120.00 FL  | *- FL      |
| 13  | 1   |          | *HEADLAMP SIDE COVER                | O/S Cut       | 190.00 FL  | *85.00 FL  |
| 14  | 1   |          | *HANDLE-BAR                         | Bent          | 150.00 FL  | *150.00 FL |
| 15  | 1   |          | *HANDLE-BAR BALANCER O/S            | Cut           | 68.00 FL   | *30.00 FL  |
| 16  | 1   |          | *SET HAND GRIP                      | Torn          | 85.00 FL   | *48.00 FL  |
| 17  | 1   |          | *BRAKE LEVER                        | Cut           | 35.00 FL   | *35.00 FL  |
| 18  | 1   |          | *BRAKE MASTER PUMP                  | Cut           | 325.00 FL  | *290.00 FL |
| 19  | 1   |          | *FUEL TANK SIDE COVER R/L/H         | O/S Cut       | 500.00 FL  | *225.00 FL |
| 20  | 1   |          | *FUEL TANK LOWER SIDE COVER - R/L/H | O/S Cut       | 250.00 FL  | *125.00 FL |
| 21  | 1   |          | *SIDE BOARD - L/H                   | Not Necessary | 150.00 FL  | *- FL      |
| 22  | 1   |          | *FRONT FOOTREST                     | O/S Cut       | 96.00 FL   | *48.00 FL  |
| 23  | 2   |          | *FRONT FOOTREST BRACKETS            | Not Necessary | 220.00 FL  | *- FL      |
| 24  | 1   |          | *BRAKE PEDAL                        | Repair        | 58.00 FL   | *- FL      |
| 25  | 1   |          | *REAR FOOTREST                      | O/S Cut       | 104.00 FL  | *48.00 FL  |
| 26  | 2   |          | *REAR SIGNAL                        | Not Necessary | 160.00 FL  | *- FL      |
| 27  | 1   |          | *EXHAUST ASSY                       | Repair        | 760.00 FL  | *- FL      |
| 28  | 1   |          | *EXHAUST CAP                        | Cut           | 65.00 FL   | *65.00 FL  |
| 29  | 1   |          | *EXHAUST PROTECTOR                  | Cut           | 95.00 FL   | *95.00 FL  |
| 30  | 1   |          | *SET NUMBER PLATE (FRONT & REAR)    | Bent / Cut    | 38.00 FS   | *20.00 FS  |
| 31  | 2   |          | *FORK OILS                          | Not Necessary | 30.00 FS   | *- FS      |
| 32  | 2   |          | *FORK OIL SEALS                     | Not Necessary | 56.00 FS   | *- FS      |
| 33  | 1   |          | *SET STEERING CONE                  | Not Necessary | 95.00 FS   | *- FS      |
| 34  | 1   |          | *E.R.P. IU                          | Cut           | 180.00 FS  | *165.00 FS |
| 35  | 1   |          | *REAR BOX                           | Cut           | 480.00 FS  | *280.00 FS |
| 36  | 1   |          | *REAR BOX BRACKET                   | Not Necessary | 180.00 FS  | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>7,605.00</b> | <b>2,786.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 654.60          | 232.10          |
| <b>Total Parts (\$)</b>                                  | <b>6,950.40</b> | <b>2,553.90</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                 | Lab.Type | Repairer's    | Amount        |
|--------------------------------|---------------------------------------------|----------|---------------|---------------|
| <b>Labour Items</b>            |                                             |          |               |               |
| 1                              | TO CHECK WIRING AND RESET HEADLAMP FOCUSING | New      | 80.00         | 0.00          |
| 2                              | TO REPAIR BODY FRAME                        | New      | 380.00        | 0.00          |
| 3                              | TO PROVIDE LABOUR                           | New      | 480.00        | 300.00        |
| <b>Gross Labour Cost (S\$)</b> |                                             |          | <b>940.00</b> | <b>300.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >