

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006724/KVY3M4**Date:** 21/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00008152200
Claimant Vehicle No :	SKS4598K	Insured Vehicle No :	PC8287G
Date of Loss:	08/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204786/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS4598K	Engine No:	L15B3514186
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11014176
Reg. Date:	16/04/2015 (Man. Year: 2014)	Odometer:	190733 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,974.80	1,845.84	4,128.96	69.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	990.00	1,220.00	55.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	8,184.80	2,835.84	5,348.96	65.35

INSPECTION

Date of Assignment:	15/07/2022	
Date Inspected:	18/07/2022	Inspected At: Poon Siang Seow (HQ) 160 Sin Ming Drive, #05-13 Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS4598K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Bent	1,100.90 F	*953.00 FL
2	1		*REAR TAIL GATE LOCK	Repair	385.90 F	*- FL
3	1		*REAR TAIL GATE DAMPER X2	Serviceable	360.80 F	*- FL
4	1		*REAR TAIL GATE RUBBER	Serviceable	168.00 F	*- FL
5	1		*REAR TAIL GATE BADGE VEZEL	Necessary	55.00 F	*55.00 FL
6	1		*REAR TAIL GATE LOGO	Not Necessary	48.00 F	*- FL
7	1		*REAR TAIL GATE OUT HANDLE	Serviceable	280.80 F	*- FL
8	1		*REAR W/S GLASS MOULDING	Necessary	186.50 F	*186.50 FL
9	1		*REAR PANEL	Repair	485.60 F	*- FL
10	1		*REAR PANEL TOP GARISH	Serviceable	192.80 F	*- FL
11	1		*REAR BUMPER	Buckled / Dented	762.80 F	*762.80 FL
12	1		*REAR BUMPER SIDE X2	Serviceable	390.00 F	*- FL
13	1		*REAR BUMPER SIDE RETAINER X2	Serviceable	128.00 F	*- FL
14	1		*REAR BUMPER SENSOR	Shorted	350.00 F	*350.00 FL
15	1		*TAIL LAMP LEFT	Serviceable	468.80 F	*- FL
16	1		*REAR BUMPER REFLECTOR X2	Serviceable	270.00 F	*- FL
17	1		*REAR TAIL GATE REFLECTOR LEFT	Serviceable	340.90 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,974.80	2,307.30
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	461.46
Total Parts (S\$)	5,974.80	1,845.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	100.00	30.00
2	TO REMOVE AND REFIT REAR W/S GLASS AND SEALANT	New	250.00	160.00
3	PANEL BEATING	New	980.00	400.00
4	SPRAY PAINTING	New	880.00	400.00
Gross Labour Cost (\$\$)			2,210.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >