



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

NEO SENG TAI
Blk 194A #08-223
Bukit Batok West Avenue 6
Singapore 651194

*Not Notified
b/c @ 2835.84
Resurvey After Painting
4 days*

Dear sir
Estimate cost of repair to vehicle no. SKS4598K
To supply

1. Rear tail gate	953.00	1,100.90	✓
2. Rear tail gate lock		385.90	X
3. Rear tail gate damper x2		360.80	✓
4. Rear tail gate rubber		168.00	✓
5. Rear tail gate badge vezel		55.00	✓
6. Rear tail gate logo		48.00	X
7. Rear tail gate out handle		280.80	X
8. Rear w/s glass moulding		186.50	✓
9. Rear panel		485.60	✓
10. Rear panel top garish		192.80	X
11. Rear bumper		762.80	✓
12. Rear bumper side x2		390.00	X
13. Rear bumper side retainer x2		128.00	X
14. Rear bumper sensor		350.00	✓
15. Tail lamp left		468.80	X
16. Rear bumper reflector x2		270.00	X
17. Rear tail gate reflector left		340.90	X
Labour charge	20%		
Rust proofing		100.00	30%
To remove and refit rear w/s glass and sealant		250.00	150%
Panel beating		980.00	40%
Spray painting		880.00	40%
Total		5,786.20	

Your faithfully

for

ALBERT POON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: