



# MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z  
 Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896  
 HP: 98888885

## Estimation

Date: 18/7/2022  
 Vehicle: SNB3504S SLV4453S  
 Make / Model: TOYOTA PRIUS  
 Chassis No:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT DOOR RH <i>bt/</i>	1	\$ 1,359.00	\$ 1,359.00
2	FRONT DOOR INNER LOCK RH <i>X</i>	1	\$ 312.00	\$ 312.00
3	FRONT DOOR REGULATOR RH <i>? X</i>	1	\$ 587.00	\$ 587.00
4	FRONT DOOR MOTOR RH <i>? X</i>	1	\$ 698.00	\$ 698.00
5	FRONT DOOR FRAME GARNISH RH <i>X</i>	1	\$ 159.00	\$ 159.00
6	FRONT DOOR FRAME BLACK STICKER RH <i>u/</i>	1	\$ 89.00	\$ 89.00
7	FRONT DOOR OUTER MOULDING RH <i>X</i>	1	\$ 198.00	\$ 198.00
8	SIDE MIRROR RH <i>? X</i>	1	\$ 681.00	\$ 681.00
9	REAR DOOR RH <i>repair</i>	1	\$ 1,258.00	\$ 1,258.00
TOTAL PART				\$ 5,341.00
LIST DOWN				25%
				\$ 1,335.25
AFTER LIST DOWN				\$ 4,005.75
SPECIAL NETT				
1	FRONT DOOR INNER TRIM CLIPS <i>u/</i>	1	\$ 50.00	\$ 50.00
TOTAL AMOUNT				\$ 200.00
LABOUR				
1	CHECK WIRING <i>X</i>	1	\$ 100.00	\$ 100.00
2	REMOVE AND REPAIR REAR DOOR MECHANISM <i>X</i>	1	\$ 150.00	\$ 150.00
3	REMOVE AND REPAIR FRONT DOOR GLASS	1	\$ 150.00	\$ 150.00
4	REMOVE AND REPAIR SIDE MIRROR RH	1	\$ 100.00	\$ 100.00
5	REMOVE AND REPAIR FRONT DOOR MECHANISM	1	\$ 150.00	\$ 150.00
6	PANEL BEAT EFFECTED AREAS	1	\$ 500.00	\$ 500.00
7	REPAIR EFFECTED AREAS	1	\$ 500.00	\$ 500.00
TOTAL AMOUNT				\$ 1,650.00
Parts Replacement Amount				\$ 4,200.00
Total Amount for Labour				\$ 1,650.00
Total Amount				\$ 5,850.00

1218.20  
 X NN  
 X NN  
 X NN  
 X NN  
 60  
 X NN  
 X NN  
 R  
 1278.20  
 25%  
 958.65

30 30

930

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

958.65  
 30.00  
 930.00  
 1918.15  
 20%  
 1534.92  
 HS- \$1,500

*Rahul*  
 Hp 9006068  
 4 days  
 4/3  
 18/07/22 @ 1600  
 Resy after repair