



Chye Thiam Maintenance Pte Ltd
14, Tampines Industrial Drive,
Singapore 528530

Attention: Owner
Contact:

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE ES010250
Date 20/7/2022
Vehicle Number XD6695A
Make / Model SCANIA P340CB6X4MHZ
Engine Number 6714978
Chassis Number XLEP6X40005290181
Accident Date 28 Jun 2022
Policy Number 5108281586-03

Description	Qty	Unit Price	Amount
Parts			
List Items			
Front Bumper L/H ✓ BT	1	S\$1,050.00	S\$987.00
Step Garnish L/H Lower ✓ QR (credit)	1	S\$550.00	S\$522.50
Front Bumper Bracket Lower R/H X	1	S\$125.00	S\$118.75
Step Garnish Inner L/H (Aluminum) ✓ QR / cm	1	S\$250.00	S\$237.50
Discount 5% applied			\$1,865.75

Labour

Labour Charge To Change All Necessary Parts	300	1	S\$850.00	S\$850.00
				\$850.00
Total				\$2,715.75

Steve (LKK)
20/7/22, 4.30 pm

m R
2 dy
L/S

Ly AL y

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which
may be require after the work has begin
is subject to final approval from Insurance Company

Acknowledged by Repairer

Pages

1 / 1