

(08/11/13) wof

ASS. REC. BY: Marcus

REF:

1CS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SGX 1388R

at Workshop m/s

Sme

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$250

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$45K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV REP. / 24 HRS

638F

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 926144

Date / Time

Action / Instruction

Dep 9k

Bonnet. Jamm can't open during survey

coe until 09-07-2027

Veh No:

SGX 1388R

Yr Regn:

10/07/07

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA / Aeris

Make:

Toyota Esteem

c.c

2362

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

22/015

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ACRSD 0036413

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55-R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

13/7/22

D.O.I.

15/7/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure effected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

) \$ + RS \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 8106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	22/EC/OD-348 (07)
Policy No:	MPC22P0098800	Date of Loss:	13/07/2022
Vehicle Reg. No.:	SGX1388R	Driveable?	
Driver Age/Info:	33 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE GUOHAO ROFIENOE	Contact No:	+6581869984
Driver:	LEE GUOHAO ROFIENOE		
Make/Model:	TOYOTA ESTIMA, 2.4 (A)	Vehicle Reg. Date:	10/07/2007
Vehicle Colour:	Black		
Engine No:	2AZF032481	Chassis No:	ACR500036413
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Remarks:	VEHICLE IN		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS	Amount
Parts	12,239.70
Miscellaneous Items	225.00
Labour	2,100.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	14,564.70
+ GST 7.00% (\$\$)	1,019.53
Nett Amount (\$\$)	15,584.23

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Not Authorized

h/le

means

15/7/22

gross \$280

h/s

telephone After repair
6 days

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 14 Jul 2022)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merliman Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	SME Motor Pte Ltd/SGX1388R/14/07/2022 13:45		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>2uc</i>	0.00	0.00	*215.00 F
2	2		*FRT BONNET HINGE <i>2uc</i>	0.00	0.00	*78.00 F
3	1		*FRT BONNET LOCK <i>2uc</i>	0.00	0.00	*85.00 F
4	1		*FRT BONNET INSULATOR	0.00	0.00	*125.00 F
5	8		*INSULATOR CLIP <i>2uc</i>	0.00	0.00	*18.00 F
6	1		*FRT BONNET LOCK CABLE <i>2uc</i>	0.00	0.00	*55.00 F
7	1		*FRT GRILLE ASSY <i>2uc</i>	0.00	0.00	*190.00 F
8	1		*FRT GRILLE LOGO <i>2uc</i>	0.00	0.00	*65.00 F
9	4		*FRT GRILLE CLIP <i>2uc</i>	0.00	0.00	*8.00 F
10	1		*FRT BUMPER <i>2uc</i>	0.00	0.00	*850.00 F
11	2		*FRT BUMPER RETAINER <i>2uc</i>	0.00	0.00	*76.00 F
12	10		*FRT BUMPER CLIP <i>2uc</i>	0.00	0.00	*20.00 F
13	1		*FRT BUMPER INNER SPONGE <i>2uc</i>	0.00	0.00	*85.00 F
14	1		*FRT BUMPER REINFORCEMENT <i>2uc</i>	0.00	0.00	*185.00 F
15	1		*FRT BUMPER CENTER BEAM <i>2uc</i>	0.00	0.00	*95.00 F
16	1		*RFT BUMPER LOWER GRILLE <i>2uc</i>	0.00	0.00	*95.00 F
17	2		*HEADLAMP <i>2uc</i>	0.00	0.00	*1,500.00 F
18	1		*HEADLAMP SUPPORT PANEL ASSY <i>2uc</i>	0.00	0.00	*550.00 F
19	1		*BRACE PANEL <i>2uc</i>	0.00	0.00	*45.00 F
20	1		*SUPPORT TOP GARNISH <i>2uc</i>	0.00	0.00	*125.00 F
21	8		*TOP GARNISH CLIP <i>2uc</i>	0.00	0.00	*18.00 F
22	1		*AIRCON CONDENSER <i>2uc</i>	0.00	0.00	*550.00 F
23	1		*RADIATOR <i>2uc</i>	0.00	0.00	*665.00 F
24	1		*RADIATOR TOP GARNISH <i>2uc</i>	0.00	0.00	*75.00 F
25	1		*RADIATOR FAN COWLING	0.00	0.00	*185.00 F
26	1		*RADIATOR FAN MOTOR	0.00	0.00	*195.00 F
27	1		*RADIATOR FAN BLADE	0.00	0.00	*95.00 F
28	1		*AIRCON FAN MOTOR	0.00	0.00	*195.00 F
29	1		*AIRCON FAN BLADE	0.00	0.00	*95.00 F
30	2		*AIRCON SIDE DEFLECTOR	0.00	0.00	*90.00 F
31	2		*AIRCON CONDENSER TOP BRACKET	0.00	0.00	*50.00 F
32	2		*RADIATOR TOP BRACKET <i>2uc</i>	0.00	0.00	*50.00 F
33	1		*WASHER TANK	0.00	0.00	*95.00 F
34	1		*WASHER TANK NECK	0.00	0.00	*35.00 F
35	1		*RADIATOR SPARE TANK	0.00	0.00	*170.00 F
36	1		*AIRCON COOLING PIPE	0.00	0.00	*385.00 F
37	1		*AIRCON DISCHARGE PIPE	0.00	0.00	*245.00 F
38	1		*AIRCON SUCTION PIPE	0.00	0.00	*315.00 F
39	1		*AIR DUCT	0.00	0.00	*95.00 F
40	1		*AIR CLEANER BOX	0.00	0.00	*400.00 F
41	1		*BATTERY BRACKET	0.00	0.00	*35.00 F
42	1		*FRT EXHAUST MANIFOLD COVER (TOP)	0.00	0.00	*175.00 F
43	2		*HID UNIT	0.00	0.00	*690.00 F
44	2		*HID BULB	0.00	0.00	*440.00 F
45	1		*ALTERNATOR	0.00	0.00	*860.00 F
46	1		*FAN BELT	0.00	0.00	*115.00 F
47	1		*FRT ENGINE MOUNTING	0.00	0.00	*85.00 F

48	1	*REAR ENGINE MOUNTING	0.00	0.00	*105.00 F	7
49	1	*RH ENGINE MOUNTING	0.00	0.00	*155.00 F	7
50	1	*LH ENGINE MOUNTING	0.00	0.00	*155.00 F	7

F=Franchise part.

Sub Total (S\$)	11,127.00
+ Margin on L,N Items 10.00% (S\$)	1,112.70

Total Parts (S\$)	12,239.70
-------------------	-----------

SME Motor Pte Ltd/SGX1388R/14/07/2022 13:45. Not valid without Reference section.
Generated using Merimon e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BATTERY	180.00
2	1	FRT NUMBER PLATE	40.00
3	1	RADIATOR COOLANT	25.00
Sub Total (S\$)			225.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00
3	REMOVE & REFIX ALTERNATOR & FAN BELT	New	120.00
4	REMOVE & REFIX 1 SET ENGINE MOUNTING	New	150.00
5	LABOUR CHARGE	New	850.00
6	SPRAY PAINTING	New	850.00
Gross Labour Cost (S\$)			2,100.00

SME Motor Pte Ltd/SGX1388R/14/07/2022 13:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >