

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Derrick Tan Ming Chye

Date: 17 Aug 2022

**Preliminary Advice**

Vehicle No	: SNC457J	Accident Date	: 26/06/2022
Make	: HONDA FREED HYBRID	Policy No.	: D18MFL0003414_02
Assignment Date	: 15/07/2022	Excess	: S\$1,500.00
Date of Inspection	: 15/07/2022	Est. Duration of Repair	: 21
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,289.40	(est \$27,214.12 + Supp \$1,075.28)
Revised Amount	:S\$	23,236.08	
Check Items (Estimated)	:S\$	1,355.20	
Total	:S\$	24,591.28	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	63,870.00
Salvage Value	:S\$	
Margin for Repair	:S\$	86,130.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Kindly approve on supplementary