

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd 64 Cecil Street #04-00 IOB Building Singapore 049711	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	---

Attn: Derrick Tan Ming Chye

Date: 15 Jul 2022

**Preliminary Advice**

Vehicle No	: SNC457J	Accident Date	: 26/06/2022
Make	: HONDA FREED HYBRID	Policy No.	: D18MFL0003414-02
Assignment Date	: 15/07/2022	Excess	: S\$0.00
Date of Inspection	: 15/07/2022	Est. Duration of Repair	: 21
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

**Point of Impact / General Description of Damages**

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 27,214.12
Revised Amount	:S\$ 22,190.16
Check Items (Estimated)	:S\$ 1,355.20
Total	:S\$ 23,545.36

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 150,000.00

COE / PARF Rebate	:S\$ 63,870.00
Salvage Value	:S\$
Margin for Repair	:S\$ 86,130.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.