

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Supplementary 1

Vehicle No : SNC457J Case Owner : 0
Make & Model : HONDA FREED Year Manufacture : 0
Chassis No : GB73132638 Engine No : 0
Sales Order : 0 Supplier : 0
Order By : _____ Type of Claim : 0

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	AIR FILTER RESONATOR		<i>CN</i>	\$ 112.00			☒
2	FRT BUMPER UNDER RUBBER		<i>Return</i>	\$ 75.00			☒
3	FRT BUMPER TOW COVER		<i>NI</i>	\$ 15.40			☒
4	LH DRIVESHAFT		<i>B</i>	\$ 1,105.00			☒
5	FRT LH ABSORBER BEARING			\$ 36.70			☒
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.