

ASS. REC. BY:

REF: AGW 220087301Kc

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Tens Cab  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SNA 4383Y Yr Regn: 06.21  
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toy Prius c.c. 1798  
 Colour: th. Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 100733 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTDKB3FU803091620  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rlm / STP / Rim or  
 Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or FIN 129  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 8 mm R/Bal. 8 mm  
 L/Bal. 8 mm L/Bal. 8 mm  
 D.O.A. 30/6/22 D.O.I. 18/7/2022  
 Survey held at \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_ Consistent?: Yes or No  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: 1.81 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
o/s body  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

Days of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:	
Transportation:	
S + RS. SI	
Fuel	
Others	
TOTAL	

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)

**Trans-cab Auto Services Pte Ltd**  
 No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
**SNA4383Y**

AAD2207-001

*Not Authorised  
 Return By paint*

Vehicle No.:  
 Chassis No.:  
 UEN No:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration:

**18 JUL 2022**

**SNA4383Y**  
**JTDKB3FU803091628**  
**201603575K**  
 TOYOTA  
 PRIUS GEN 4  
 30/06/2022  
**SDR668G/AUTO & GENERAL**  
 24/06/2021

**PART**

**LIST**

PART	LIST
1 RIM	\$ <i>Sn</i> 1,900.10 X
1 HUB CAP	\$ <i>Sn</i> 211.50 X
1 COVER, FRONT BUMPER	\$ <i>Sn</i> 521.00 X
1 LINER, FRONT FENDER, RH	\$ <i>Sn</i> 210.30 X
1 FENDER SUB-ASSY, FRONT RH	\$ <i>n</i> 977.80 X
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ <i>By</i> 1,300.70 ✓
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$ <i>n</i> <i>Sn</i> 193.50 X
1 HANDLE ASSY, FRONT DOOR OUTSIDE, RH	\$ <i>Sn</i> 390.60 X
1 WEATHERSTRIP, FRONT DOOR, RH	\$ <i>Sn</i> 231.30 X
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$ <i>n</i> 110.60 X
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$ <i>n</i> 97.50 X
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ <i>n</i> 13.30 ✓
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ <i>n</i> 43.50 ✓
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ <i>n</i> 26.30 ✓
1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$ <i>Sn</i> 926.00 X
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$ <i>Sn</i> 238.30 X
1 PANEL SUB-ASSY, REAR DOOR, RH	\$ <i>n</i> 1,294.90 X
1 MOULDING, FRONT DOOR WINDOW FRAME, REAR RH	\$ <i>Sn</i> 56.50
1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$ <i>Sn</i> 193.50
1 HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$ <i>Sn</i> 97.40
1 WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$ <i>Sn</i> 293.00
1 HINGE ASSY, REAR DOOR, LOWER RH	\$ <i>n</i> 87.10
1 HINGE ASSY, REAR DOOR, UPPER RH	\$ <i>n</i> 98.90
1 TAPE, BLACK OUT, NO.1 REAR RH	\$ <i>n</i> 21.90
1 TAPE, BLACK OUT, NO.2 REAR RH	\$ <i>n</i> 34.90
1 TAPE, BLACK OUT, NO.3 REAR RH	\$ <i>n</i> 15.40
1 MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$ <i>Sn</i> 926.00
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$ <i>Sn</i> 206.70
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$ <i>n</i> 594.80

2

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2207-001

**SNA4383Y**

- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH

	\$	<i>871.50</i>	X
	\$	<i>139.80</i>	X
<b>TOTAL</b>	<b>\$</b>	<b>12,324.60</b>	
<b>25%</b>	<b>\$</b>	<b>3,236.90</b>	
	<b>\$</b>	<b>9,710.70</b>	

**Special Nett**

2SET DOOR TRIM CLIP	\$	<i>70.00</i>	X
2SET DOOR WEATHERSTRIP CLIP	\$	<i>130.00</i>	X
1SET CLIP, ROCKER PANEL MOULDING	\$	<i>65.00</i>	X
1 FRT BUMPER CLIP	\$	<i>65.00</i>	X
1SET FENDER CLIP	\$	<i>130.00</i>	X
1 FENDER LINER CLIP	\$	<i>65.00</i>	X

<b>TOTAL</b>	<b>\$</b>	<b>525.00</b>
--------------	-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>10,235.70</b>
--------------------	-----------	------------------

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>380.00</i>	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	<i>4001</i>
To transfer of door fittings, attachment to facilitate bodywork repair.	\$	380.00	<i>601</i>
Putty And Spray Painting Of The Affected Portion.	\$	2,000.00	<i>6601</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>170.00</i>	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To check steering geometry and computer wheel alignment	\$	<i>220.00</i>	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SNA4383Y**

**AAD2207-001**

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ *~* 170.00 X

**TOTAL** \$ 5,730.00

**Over All Total** \$ 15,965.70

**(PART-BY-PART) Repair Days**

*10 Days*

*4 days*

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 30/06/2022 15:19 (SGT)  
Reported by ..... Both  
Date of Accident ..... 30/06/2022 07:05 (SGT)  
Exact Location of Accident ..... Lor 8 Geylang, Singapore  
Additional Location Information ..... LORONG 8 GEYLANG TURNING TO MAIN ROAD GEYLANG ROAD  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SNA4383Y  
INSURED/POLICYHOLDER  
Is company? ..... Yes  
Name Of Registered Owner ..... TRANS LEASING PTE LTD  
Company Reg No ..... 2XXXXX575K  
Email Address ..... claims@transcab.com.sg  
Mobile Phone No ..... (Phone) +65-65552222  
Alternative Phone No ..... -

## VEHICLE PARTICULARS

Manufacturer ..... Toyota  
Model ..... Prius  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private hire  
Transmission ..... Auto  
CC ..... 1767


## INSURANCE COMPANY

Name of Insurance Company ..... AXA Insurance Pte Ltd  
Policy Number / Cover Note Number ..... VFX/P2440417

## DRIVER

Name of Driver ..... KHO CHUAN KOK PHILIP  
NRIC No ..... SXXXX534Z  
Date Of Birth ..... 17/10/1960

ACCIDENT DIAGRAM



veh A: SNA4383Y  
 veh B: SDR668G

**VERIFIED BY AJAX MARS (ARC)  
 REPORTING OFFICER  
 ANG QI HAO, VICTOR**

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.: