



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Budget Direct Insured's Veh No : SMF2742T
Date of Accident : 09 July 2022

Mr Lin Boon Chee

Date : 09 July 2022

Estimate To Repair SMU7255X - Toyota PRIUS HYBRID 1.8S CVT
Chassis No : ZVW516146022

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper	\$ de 549.00
02	1 pc	rear bumper tow cover	\$ mis 55.00
03	8 ps	rear bumper clips @ \$4.50	\$ rel 36.00
04	2 ps	rear bumper side retainer @ \$45.00	\$ nnx 90.00
05	1 pc	rear bumper lower pad	\$ de 489.08
06	1 pc	rear bumper beam	\$ nnx 205.70
07	2 ps	rear bumper bracket @ \$139.60	\$ nnx 279.20
08	1 pc	tailgate lid	\$ nnx 1,096.10
09	1 pc	tailgate lid Prius bdge	\$ nnx 85.60
10	1 pc	tailgate lid hybrid Synergy drive badge	\$ nnx 99.80
11	1 pc	tailgate lid outer garnish	\$ Rx 824.00
12	2 ps	tail lamp @ \$417.30	\$ x 834.60
13	1 pc	rear end panel	\$ x 658.00
14	1 pc	rear end panel top garnish	\$ x 195.70
15	1 pc	rear end panel weatherstrip	\$ x 254.10
Less 25 %			\$ 5,751.88
			\$ 1,437.97
			\$ 4,313.91
<u>SPECIAL NETT ITEMS</u>			
16	1 set	rear bumper parking sensor	\$ 350.00
17	1 pc	rear windscreen glass sealant	\$ 80.00
18	1 pc	rear licence plate	\$ 50.00
			\$ 480.00
<u>LABOUR & MISC. CHARGES</u>			
01		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 60.00
02		To remove and refit rear windscreen glass.	\$ 120.00
03		To reinstall of rear bumper parking sensor.	\$ 50.00
04		To reinstall of reverse camera	\$ 50.00
05		To check electrical lighting concerned.	\$ 60.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 200 680.00
07		Putty and spray painting of the affected portion.	\$ 200 700.00
			\$ 1,720.00
Total			\$ 6,513.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749 / 62563561

wp 21/7/22 e p15

Total taufik @ 1khauto.wir.

1/8 Resurvey after repair

846.96

200

630

1676.46

4/3/1300

2 delays

1129.28

846.96

200nw

x nn

x nn

200

x nn

x nn

30

x nn

x nn

200

200

400

630