



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22006744/Acy3q2	
			Date: 01/12/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SG 6324P	Veh. Inspected	SLH 262B
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22002148MFBP	Excess (\$)	0.00
	Assign From	CAROLINE CABRERA	Assign Date	15/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053BK4107044420	Colour	BLACK
	Odometer	198354 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	215/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	215/60 R16	WEST LAKE	6 mm
	L/H Rear Tyre	215/60 R16	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/07/2022	Inspection Date	15/07/2022
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	