

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLJ5789E

TP/BD

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 62212111

FAX: 67250853

ATTN: Motor Claim Department

Estimate No: ES2290752/WS

Date: 29 Jul 2022

Policy No: 5096444419-04

Veh Reg No: SLJ5789E

Make/Model: TOYOTA TOYOTA
HARRIER PREMIUM
2.0A

Chassis No: ZSU600088068

Engine No: 3ZRB871979

Reg. Date: 16/12/2016

WS Ref: TP/BD

Claim Type: Third Party

Accident Date: 11/07/2022

TP Veh Reg No: SNA2183X

Not Not hair
1/1 Rep &

Runny After Rain
3 days

Estimate Repair Cost to Vehicle No :SLJ5789E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	663.90	1 PC	663.90	✓
2 FRONT BUMPER RH SIDE RETAINER	115.20	1 PC	115.20	?
3 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	—
4 FRONT RH FENDER	863.10	1 PC	863.10	—
			1,663.20	
		Less 25%	415.80	1,247.40
Labour				
5 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMP,FRT RH FENDER,CHECK HEADLAMP AND REALIGN THE SAME	500.00	1 LA	500.00	400
6 PUTTY & RESPRAY ON FRT BUMPER,FRT RH FENDER	550.00	1 LA	550.00	400
			1,050.00	1,050.00
			Total	S\$ 2,297.40
			Add GST @ 7%	160.82
			Total Amount Payable	S\$ 2,458.22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Parts \$1548
25% 387
\$1161
800
\$1961

U/S = \$1550