



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Lee See Kon 458 Choa Chu Kang Avenue 4 #08-207 Singapore 680458 Mobile: 90094497
	Document No. 0	
	Document Date 14/07/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZRE171R	GEXGPZ S1	09/01/2018	SLV6456X	0	16375	65DS/SLV6456X

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH604576498	1ZR0A55239	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : T/P VEH. : SG5778U ACC DATE : 13.07.22 BY :				100.00
2	B	BP-MECH2 RESET AND REPROGRAMME ECU.				180.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
4	B	BP-LAB2 CHK WIRING SYSTEM AND CONDUCT WATER TEST.				180.00
5	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				180.00
6	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR.				360.00
7	B	BP-LAB2 REMOVE AND REINSTALL REAR W/SCREEN TO ASSIST REPAIR.				450.00
8	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, R/R FENDER AND AFFECTED PORTION OF CAR.				3600.00
9	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				2360.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Lee See Kon 458 Choa Chu Kang Avenue 4 #08-207 Singapore 680458 Mobile: 90094497			
			Document No. 0					
			Document Date 14/07/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZRE171R	GEXGPZ S1	09/01/2018	SLV6456X	0	16375	65DS/SLV6456X	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053REH604576498		1ZR0A55239	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
10	1	S52159-0Z904 COVER, RR BUMPER			1.00	602.60		602.60
11	2	S52023-02190 REINFORCEMENT SUB-AS			1.00	432.50		432.50
12	3	S52591-02301 SEAL, RR BUMPER SIDE			1.00	59.70		59.70
13	4	S52575-02140 RETAINER, RR BUMPER			1.00	118.70		118.70
14	5	S52562-02250 RETAINER, RR BUMPER,			1.00	65.60		65.60
15	6	S52161-0K040 PIECE, RR BUMPER			2.00	4.50		9.00
16	7	S52181-02190 ARM, RR BUMPER, OUTE			1.00	73.70		73.70
17	8	S61601-02270 PANEL SUB-ASSY, QUAR			1.00	1244.80		1244.80
18	9	S61697-02913 HOUSING, QUARTER PAN			1.00	120.50		120.50
19	0	T21000-20 SIKI 182010 SIKI TACK GO! (BLA			2.00	108.00		216.00
20	1	T21000-22 SIKI 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00
21	2	T08826-08115 PANEL BONDING AD			1.00	267.20		267.20
22	3	S81580-02A70 LAMP ASSY, RR, RH			1.00	509.80		509.80
23	4	S81550-02B20 LAMP ASSY, RR COMBIN			1.00	539.50		539.50
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle 		Parts		11,969.60	
					Labour		837.87	
					Sublet		0.00	
					Lubrication/Fluid		0.00	
					Others		0.00	
					GST 7.00%		12,807.47	
					Less		0.00	
					Amount Due		12,807.47	

Customer Copy