

ASS. REC. BY:

REF:

ASM 22 006753/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / LWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFO 33014

Yr Regn:

04, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M B200

c.c.

1595

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

144095

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD-2462431146995

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: B.S

205/55R16

R: Pir

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

14/7/22

D.O.I.

18/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1) GIA not ready LTA value @ 13,640.00

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

) \$ + RS. \$

) P. 25

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 20082 0153N

Date : 15 / 07 / 2022

ESTIMATE	COSTS	OF	REPAIR
----------	-------	----	--------

Ms Lo Kua Chiung

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SFD 3301 U - Mercedes Benz B200 AT
Accident date : 14 / 07 / 2022

*Not Autherized
11 Rep &
Money After Rain
7 days*

Quantity	Descriptions	Amount (S\$)
----------	--------------	----------------

1	1 pc	n/s front fender <i>Rx</i>	
2	1 pc	n/s front door <i>Rx</i>	
3	1 pc	n/s front door rubber <i>Sm x</i>	
4	2 pcs	n/s front door hinge 1 @ 122.00 <i>Rx</i>	
5	1 pc	n/s front door inner lock <i>Rx</i>	
6	1 pc	n/s front door glass outer molding <i>Sm x</i>	
7	1 pc	n/s front door side mirror <i>Sm y</i>	
8	1 pc	n/s front door side mirror cover <i>Sm x</i>	
9	1 pc	n/s rear door <i>Red/way</i>	
10	1 pc	n/s rear door rubber <i>Sm 508in</i>	
11	1 pc	n/s rear door glass outer molding <i>Sm x</i>	
12	2 pcs	n/s rear door hinge 1 @ 122.00 <i>Rx</i>	
13	1 pc	n/s rear door inner lock <i>Rx</i>	
14	1 pc	n/s rocker panel garnish <i>Rx</i>	
15	1 pc	rear bumper <i>msc m</i>	
16	2 pcs	rear bumper side moulding 1 @ 179.00 <i>msc</i>	
17	1 pc	n/s rear fender <i>Rx</i>	
18	1 pc	n/s rear fender inner garnish <i>Sm x</i>	
19	1 pc	n/s rear lower arm ?	} <i>wheel Alignment report</i>
20	1 pc	n/s rear trailing arm ?	
21	1 pc	n/s rear shock absorber ?	
22	1 pc	n/s rear upper arm <i>Rx m</i>	
23	1 pc	n/s rear control arm ?	
24	1 pc	n/s rear knuckle arm ?	
25	1 pc	n/s rear knuckle arm bearing ?	
26	1 pc	n/s rear anti roll bar side link <i>Sm x</i>	

Less 10 %

Balance C/FD

\$	-
\$	-
\$	-

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 20082 0153N

		Balance B/FD (SKG 8108 D)	\$ -
43	1 pc	n/s rear quarter glass inner seal <i>nn x</i>	sn
44	1 pc	n/s rear quarter glass inner gum <i>nn x</i>	sn
47	1 pc	n/s rear wheel rim <i>nn</i>	sn
48	1 pc	n/s rear wheel tyre <i>nn x</i>	sn
			\$ -

Labour charges	\$ 1,800.00	<i>600</i>
To putty and spray painting	\$ 1,600.00	<i>1100</i>
To re-seal anti rust	\$ 350.00	<i>30</i>
To check, replace, repair wiring, re-set fault code	\$ 450.00	<i>7</i>
To transfer n/s rear door & n/s front door	\$ 250.00	<i>60</i>
Remove and refix cushion seat, garnish, carpet	<i>nn</i> \$ 280.00	<i>x</i>
Remove and refix fuel tank	<i>nn</i> \$ 280.00	<i>x</i>
Remove and refix n/s rear & front undercarriage	\$ 350.00	<i>?</i>
To check wheel alignment	\$ 120.00	<i>60</i>
	\$ 5,480.00	
Plus 7% GST	\$ 383.60	
Sub-Total	\$ 5,863.60	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: