

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE 510607
BUSINESS REGN. No. 53193457L
Email: willybjt@gmail.com / Mobile: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Muhammad Nurraihan Bin Abdul Ghani
c/o Goh JP & Wong LLC
133 New Bridge Road # 16-09
Chinatown Point
Singapore 059413

Our Ref : PA/FBA886/0222/tpw
Date : 11 March 2022

REFERENCES

Claim Type	: Third Party	Date of Accident	: 16 February 2022
Vehicle No	: FBA 886 G	Date of Assignment	: 23 February 2022
Make	: Honda	Date of Inspection	: 23 February 2022
Model	: CB400	Date of Re-inspection	: 24 Feb & 03 Mar 2022
Registration Date	: 25 January 2006	COE Expiry	: 28 February 2025
Color	: Black	Chassis No	: JH2NC39955M100022
Odometer	: Meter damaged	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Pirelli	120/60-17	5mm
Rear	Pirelli	160/60-17	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and both sides.
Please refer to photographs and assessment of repairs for details
Enclosed (66) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$9,343.64 Revised Assessment \$6,500.00 Lump sum

Survey conducted at Wing Fuat Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately Six (6) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock reconditioned parts whichever is possible

- Photos after repair

showed damaged parts on ground.

- Part prices checked and found reasonable.

- Damages shown by photos.

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBA 886 G

Our Ref: PA/FBA886/0222/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

<u>S/N</u>	<u>Description Material</u>	<u>Qty</u>	<u>Condition</u>	<u>Original Quotation</u>	<u>Revised Quotation</u>	
1	Handle bar	1 pc	Bent	160.00	160.00	✓
2	Handle bar balancer	1 set	Cut	60.00	60.00	✓
3	Handle grip	1 pc	Serviceable	42.00	-	✓ SN
4	Brake lever	1 pc	Cut	31.50	31.50	✓
5	Mirror	1 set	Cut	130.00	130.00	✓
6	Meter complete	1 pc	Cracked	1,120.00	1,120.00	✓
7	Front winker light assy @ \$85/-	2 pcs	Cracked	170.00	170.00	✓
8	Headlight assy	1 pc	Scratch	368.00	368.00	✓
9	Headlight case	1 pc	Cracked	125.50	125.50	✓
10	Headlight stay	1 pc	Distorted	75.00	75.00	✓
11	Headlight plate @ \$58/-	2 pcs	Distorted	116.00	116.00	✓
12	Front fork assy @ \$978.60/-	2 pcs	Bent LH	1,957.20	978.60	✓
13	Front fender	1 pc	Cut	145.00	145.00	✓
14	Front wheel complete	1 pc	Cut	720.00	720.00	350.00 SN
15	Front brake disc RH	1 pc	Warped	420.00	420.00	✓
16	Fuel tank assy	1 pc	Dented	980.00	980.00	✓
17	Radiator assy	1 pc	Dented	659.40	659.40	✓
18	Crankcase cap cover	1 pc	Grazed/cut	102.00	102.00	✓
19	Front footrest assy RH	1 pc	Cut/bent	78.00	78.00	✓
				7,459.60	6,439.00	
List price less discount 10%				745.96	643.90	
				6,713.64	5,795.10	
<u>Special Nett Items</u>						
20	Exhaust muffler (Yoshimura)	1 pc	Dented/grazed	1,280.00	1,280.00	✓
21	Engine guard	1 set	Cut	350.00	280.00	✓
				1,630.00	1,560.00	
<u>Labours</u>						
Towing (2 trips)				150.00	120.00	60/-
Body chassis repair and alignment				350.00	280.00	150/-
To remove, renew accident damaged parts				500.00	400.00	250/-
				1,000.00	800.00	
Total Parts & Labours Concluded				9,343.64	8,155.10	
Final Lump Sum Repair Adjustment				7517.10	6,500.00	

5719.00

5147.10

10%

1910.00

460.00

4/5 6,000/- 4 days.

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBA 886 G**

Our Ref: PA/FBA886/0222/tpw

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.



Prudent Adjustors Services
Bok Jee Tan