

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD9516D

Not Available
11 Sep @ 4100h

AAD2207-

Vehicle No.:
Chassis No.:
Co UEN:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

13 JUL 2022

SHD9516D

JTDKB3FU203081435

200303878K

TOYOTA

PRIUS

12/07/2022

GBC5878L/CHINA

27/06/2019

PART

LIST

1 COVER, REAR BUMPER	\$	Bu	442.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	Bu	332.70	✓
1 COVER, REAR BUMPER, LOWER	\$	Bu	15.40	✓
1 GUARD, REAR BUMPER, CENTER	\$	Bu	576.30	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$	Sm	116.50	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	Sm	117.70	✓
1 FILLER, REAR BUMPER EXTENSION, RH	\$	Sm	123.70	X
1 MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	\$	Sm	54.40	X
1 LENS AND BODY, REAR LAMP, LH (LOWER)	\$	Sm	502.00	X
1 LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)	\$	Sm	443.30	X
1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$	Sm	451.80	X
1 LENS AND BODY, REAR LAMP, RH (LOWER)	\$	Sm	502.00	X
1 PANEL SUB-ASSY, BACK DOOR	\$	Bu	1,147.80	✓
1 BOARD, REAR FLOOR, NO.1	\$	Sm	519.00	X
1 BOX, DECK FLOOR, LH	\$	Sm	313.00	X
1 BOX, DECK FLOOR, RH	\$	Sm	313.60	X
1 BOX, DECK FLOOR, REAR	\$	Sm	105.80	X
1 SPOILER SUB-ASSY, REAR	\$	R	1,575.40	X
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	cm	925.60	✓
1 COVER, FLOOR UNDER, NO.1 LH	\$	Sm	175.10	X
1 COVER, FLOOR UNDER, NO.2 RH	\$	Sm	241.90	X
1 COVER, REAR FLOOR CTR	\$	Sm	229.90	X
1 COVER, DECK TRIM, REAR	\$	Sm	126.70	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	R	650.30	X
1 SEAL, REAR BUMPER SIDE, RH	\$	Sm	88.50	X
1 STAY ASSY, BACK DOOR, LH	\$	Sm	242.50	X
1 STAY ASSY, BACK DOOR, RH	\$	Sm	242.50	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2207-

SHD9516D

1	HINGE ASSY, BACK DOOR, LH	\$	na	61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	na	61.00	X
1	REAR TAILGATE TOYOTA LOGO	\$	na	47.90	✓
1	REAR TAILGATE WORDING 'PRIUS'	\$	na	54.60	✓
1	REAR TAILGATE WORDING 'HYBRID'	\$	na	54.60	✓

TOTAL \$ 10,855.10**25% \$ 2,713.78****\$ 8,141.33****Special Nett**

1SET PARKING AID	\$	na	700.00	2205AL
1 REAR SPOILER CLIP	\$	na	65.00	X
1SET REAR BUMPER CLIP	\$	na	95.00	601AL
2 WINDSCREEN SEALANT	\$	na	150.00	801AL
1 WINDSCREEN MOULDING	\$	na	200.00	✓
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	301AL
1 REAR TAILGATE STICKER "Trans-Cab"	\$	na	80.00	301AL
1 REAR TAILGATE STICKER "6555-3333"	\$	na	80.00	301AL
1 REAR BUMPER PROTECTOR	\$	na	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	na	85.00	X
1 END PANEL TRIM CLIP	\$	na	65.00	X

TOTAL \$ 1,830.00**TOTAL PARTS \$ 9,971.33****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 1801

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 601

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 6001

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2207-

SHD9516D

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	601
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Towing Fees	\$	nn 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	6601
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 220.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn 380.00	X
TOTAL	\$	8,920.00	

Trans-cab Auto Services Pte Ltd

AAD2207-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9516D**Over All Total \$ 18,891.33****(PART-BY-PART) Repair Days 25 DAYS***4 days*

Date of Submission 18/07/2022 00:15 (SGT)
 Date of Accident 18/07/2022 00:15 (SGT)
 Location of Accident Singapore
 Local Location Information 25/00K NORTH AVENUE 1
 City/State of Loss

Registration Number SHD9516D
 Registered Owner
 Any Reg No
 Address
 Phone No
 Mobile Phone No

Vehicle Make Toyota
 Model Prius
 EDR MATCHBOOK (AUTO)
 Purpose for which vehicle was being used at time of accident Private Hire
 Claiming under your own insurance policy for repair to vehicle? No - Claiming third party
 Category Taxi
 Reason Auto
 1757

Insurance Company AXA Insurance Pte Ltd
 Policy No. 201019626G

Driver LIM QIN SEONG
 License No. H10003170
 Date of Birth 28/10/1981
 Gender Male

Print report SA10227C0000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: