

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD357E*Not Authored
L/Sing &*

AAD2207-

Vehicle No.:
 Chassis No.:
 UEN No:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

13 JUL 2022**SHD357E**

VF1ABL15AUC282678

200303878K

RENAULT

LATITUDE

10/07/2022

SLE8651A/AIG

17/05/2016

PART	LIST		
1 BUMPER COVER FRT	\$	<i>BH/CM</i> 747.20	✓
1 BUMPER UNDERTRAY FRT	\$	<i>sea</i> 292.50	✓
1 BUMPER SPOILER FRT	\$	<i>DIT</i> 344.70	✓
1 BUMPER ABSORBER FRT	\$	<i>su</i> 394.68	✓
1 BUMPER BRACKET KIT FRT LH	\$	<i>su</i> 101.40	X
1 BUMPER RETAINER FRT LH	\$	<i>su</i> 101.40	✓
1 BUMPER BRACKET KIT FRT RH	\$	<i>su</i> 101.40	✓
1 BUMPER RETAINER FRT RH	\$	<i>CM</i> 101.40	✓
1 BUMPER SUPPORT FRT	\$	<i>su</i> 10.70	X
1 BUMPER BRACKET FRT RH (Headlamp Lower)	\$	<i>CM</i> 116.47	✓
1 BUMPER GRILLE LOWER FRT	\$	<i>su</i> 147.00	X
1 BUMPER FOG LAMP GRILLE LH	\$	<i>su</i> 207.21	✓
1 BUMPER FOG LAMP GRILLE RH	\$	<i>su</i> 207.21	✓
1 TOW COVER FRT	\$	<i>su</i> 60.90	X
1 FENDER PANEL FRT RH	\$	<i>Ry</i> 437.10	✓
1 WHEELARCH FRT RH	\$	<i>CM</i> 191.40	✓
1 BUMPER UNDERTRAY FRT	\$	<i>su</i> 292.50	✓
1 RADIATOR GRILLE	\$	<i>su</i> 969.90	✓
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>su</i> 225.36	✓
1 RADIATOR GRILLE FRAME	\$	<i>su</i> 686.00	✓
1 FRAME FULL SUPPORT PANEL	\$	<i>su</i> 592.70	✓
1 WIPER RESERVOIR	\$	<i>nu</i> 179.60	✓
1 HEADLAMP RH	\$	<i>my CM</i> 743.60	✓
	\$	7,252.33	
10%	\$	725.23	
	\$	6,527.09	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD357E

AAD2207-

Special Nett

1 FRONT BUMPER CLIP	\$	nn 66.00	✓
1 LICENSE PLATE WITH HOLDER FRT	\$	pn 121.00	X
1 FENDER LINER CLIP	\$	nn 65.00	✓
1 FRONT UNDERTRAY CLIP	\$	nn 65.00	X
TOTAL	\$	317.00	
TOTAL PARTS	\$	6,844.09	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 300.00	X
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD357E

AAD2207-

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>2cl</i>
TOTAL	\$	7,880.00	
Over All Total	\$	21,251.19	

(LUMP SUM)

Repair Days

20 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/07/2022 22:38 (SGT)
Reported by Driver
Date of Accident 10/07/2022 19:30 (SGT)
Exact Location of Accident Bras Basah Rd, Singapore
Additional Location Information JUNCTION OF BRAS BASAH ROAD AND VICTORIA ST
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD357E

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXX878K
Email Address Claims@transcab.com.sg
Mobile Phone No (Phone) +65-62876666
Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Renault
Model Latitude
Variant 2.0L DCI AUTO D/AB 4DR
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1998

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Policy Number / Cover Note Number VFX/P2413997

DRIVER

Name of Driver KOO KIM TECK
NIC No SXXXX390B
Date Of Birth 10/04/1970
Occupation Outdoor

Date Of Driving Pass	18/06/2009
Driving experience	13 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-82720511
Alt. Phone Number	-
Email Address	Claims@transcab.com.sg
Address	551 BEDOK NORTH AVE 1
Address complement	#04-540
Postcode	460551
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 10/7/2022 AT ABOUT 1930HOURS , I WAS TRAVELLING ALONG BRAS BASAH ROAD TOWARDS MARINA . WHEN I DRIVING STRAIGHT ALONG MOST LEFT LANE , SUDDENLY VEHICLE B FROM MY RIGHT LANE TURNING LEFT AND COLLIDED ONTO RIGHT FRONT SIDE OF MY VEHICLE .



ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE8651A
Vehicle Manufacturer	Honda
Vehicle Model	VezeL
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

ACCIDENT REPORT



do

Police Officer's Signature / Title & Date

Witness's Signature (If different to the police officer) / Title & Date

Witnessed By Reporting Officer
Wong Jui Kiat
Witnessed By Reporting Centre
Personnel