

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD357E**

*Not Authored  
21 Pmg @ 2900/hr*

AAD2207-

Vehicle No.:  
Chassis No.:  
UEN No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

13 JUL 2022

**SHD357E**  
VF1ABL15AUC282678  
200303878K  
RENAULT  
LATITUDE  
10/07/2022  
**SLE8651A/AIG**  
17/05/2016

| PART                                     | LIST                    |   |
|--|-------------------------|---|
| 1 BUMPER COVER FRT                       | \$ <i>B/CMT</i> 747.20  | ✓ |
| 1 BUMPER UNDERTRAY FRT                   | \$ <i>SEA</i> 292.50    | X |
| 1 BUMPER SPOILER FRT                     | \$ <i>D-17</i> 344.70   | ✓ |
| 1 BUMPER ABSORBER FRT                    | \$ <i>SM</i> 394.68     | X |
| 1 BUMPER BRACKET KIT FRT LH              | \$ <i>SM</i> 101.40     | X |
| 1 BUMPER RETAINER FRT LH                 | \$ <i>SM</i> 101.40     | X |
| 1 BUMPER BRACKET KIT FRT RH              | \$ <i>SM</i> 101.40     | X |
| 1 BUMPER RETAINER FRT RH                 | \$ <i>CMT</i> 101.40    | ✓ |
| 1 BUMPER SUPPORT FRT                     | \$ <i>SM</i> 10.70      | X |
| 1 BUMPER BRACKET FRT RH (Headlamp Lower) | \$ <i>CMT</i> 116.47    | ✓ |
| 1 BUMPER GRILLE LOWER FRT                | \$ <i>SM</i> 147.00     | X |
| 1 BUMPER FOG LAMP GRILLE LH              | \$ <i>SM</i> 207.21     | X |
| 1 BUMPER FOG LAMP GRILLE RH              | \$ <i>SM</i> 207.21     | X |
| 1 TOW COVER FRT                          | \$ <i>SM</i> 60.90      | X |
| 1 FENDER PANEL FRT RH                    | \$ <i>BY</i> 437.10     | ✓ |
| 1 WHEELARCH FRT RH                       | \$ <i>CMT</i> 191.40    | ✓ |
| 1 BUMPER UNDERTRAY FRT                   | \$ <i>SM</i> 292.50     | X |
| 1 RADIATOR GRILLE                        | \$ <i>SM</i> 969.90     | X |
| 1 RADIATOR GRILLE BADGE 'RENAULT'        | \$ <i>SM</i> 225.36     | X |
| 1 RADIATOR GRILLE FRAME                  | \$ <i>SM</i> 686.00     | X |
| 1 FRAME FULL SUPPORT PANEL               | \$ <i>SM</i> 592.70     | X |
| 1 WIPER RESERVOIR                        | \$ <i>ND</i> 179.60     | ✓ |
| 1 HEADLAMP RH                            | \$ <i>MY CMT</i> 743.60 | ✓ |
|  | \$ <b>7,252.33</b>      |   |
|  | 10% \$ <b>725.23</b>    |   |
|  | \$ <b>6,527.09</b>      |   |

**Trans-cab Auto Services Pte Ltd**

AAD2207-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD357E

**Special Nett**

|                    |                               |           |           |                 |   |
|--------------------|-------------------------------|-----------|-----------|-----------------|---|
| 1                  | FRONT BUMPER CLIP             | \$        | <i>na</i> | 66.00           | ✓ |
| 1                  | LICENSE PLATE WITH HOLDER FRT | \$        | <i>na</i> | 121.00          | X |
| 1                  | FENDER LINER CLIP             | \$        | <i>na</i> | 65.00           | ✓ |
| 1                  | FRONT UNDERTRAY CLIP          | \$        | <i>na</i> | 65.00           | X |
| <b>TOTAL</b>       |                               | <b>\$</b> |           | <b>317.00</b>   |   |
| <b>TOTAL PARTS</b> |                               | <b>\$</b> |           | <b>6,844.09</b> |   |

**LABOUR**

|   |    |           |          |             |
|---|----|-----------|----------|-------------|
| To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.                                      | \$ | <i>na</i> | 300.00   | X           |
| Putty And Spray Painting Of The Affected Portion.   | \$ |           | 3,000.00 | <i>4401</i> |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ |           | 3,000.00 | <i>4001</i> |
| To Rust-Proofing Of The Affected Areas.   | \$ |           | 170.00   | <i>301</i>  |
| To reinstall rear bumper parking sensor.  | \$ | <i>na</i> | 170.00   | X           |
| To transfer of bootlid fittings, attachments and perform water seepage test.  | \$ | <i>na</i> | 170.00   | X           |
| To repair and realign rear exhaust pipe.  | \$ | <i>na</i> | 170.00   | X           |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.                                      | \$ | <i>na</i> | 170.00   | X           |
| To transfer of rear end panel fittings, attachment and perform water seepage test.  | \$ | <i>na</i> | 170.00   | X           |
| To transfer of rear windscreen fittings and conduct water seepage test.   | \$ | <i>na</i> | 170.00   | X           |

**Trans-cab Auto Services Pte Ltd**

AAD2207-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD357E**

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To Check Electrical Lighting Concerned. \$ 170.00 *201*

**TOTAL \$ 7,880.00**

**Over All Total \$ 21,251.19**

**(LUMP SUM)**

**Repair Days *20 DAYS***  
*2 days*

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: