

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated : 01/08/2022 User ID PohSuan

	Section A - Accident Details
Registration Number	SHB5792J
Case Reference Number	TAX/07/22/2038
Registration Date	12/12/2017
Company Type	Strides Taxi Pte Ltd
Make	ТОУОТА
Model	PRIUS4
Name of Driver	TAN CHIN HENG
Type of Accident	Head to Rear
Accident Date and Time	14/7/2022 1:31 PM
Accident Reported Date and Time	14/7/2022 2:36 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115612
Special Instruction to ARC,if	FRONT PORTION
Prepared Date and Time	14/7/2022 5:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates Summary of Repair Estimates							
Total Labour Cost	\$676.00	\$200.00					
Total Spray Cost	\$558.00	\$200.00					
Total Spare Part Cost	\$6,282.25	\$2,751.22					
Total Other Cost	\$380.00	(\$601.22)					
TOTAL COST	\$7,896.25	\$2,550.00 (L/S)					
Lump Sum Total	\$0.00	\$0.00					
Number of Repair Days	4.0	3.0					
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC					
ARC / Surveyor Sign Off Date	15/07/2022 4:03 PM	15/07/2022 2:34 PM					
Signature		Rosm					
Remarks		resurvey after repair lum sump					



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63885592 Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

Date Generated : 01/08/2022 User ID PohSuan

Section C - Quotation and Accident Invoice Details								
Quotation Number QN-2207-0418 Invoice Number								
Quotation Date	28.07.2022	Invoice Date						
Invoice Amount Prepared Date								

Section D - Details of Repair Estimates						
Part 1 - Labour Works						
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable				
TO REPAIR FRONT PORTION	\$676.00	\$200.00				
Total Labour	\$676.00	\$200.00				

Part 2 - Spray Painting & Panel Beating Related Works						
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable				
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00				
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00				
Total Spray Painting & Panel Beating	\$558.00	\$200.00				

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO WASH AND VACUUM	\$60.00	\$0.00		
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00		
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00		
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00		
Lump Sum Adjustment by Surveyor	\$0.00	(\$631.22)		
Total Other Costs	\$380.00	(\$601.22)		

Part	Portion	Stock	Part Name	Quantity	List Price	Discount	Final Price	Estimator	Surveyor
Number		Number			(\$)	(%)	(\$)	Approved	Approved
		52119479	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		62							
		52115470	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Check
		50							
		52116470	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given
		50							
		52127479	COVER, FR BUMPER RH	1.00	\$28.10	100.00	\$0.00	Replace	Repair
		07							
			BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Not Given
		90							
			NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE	0.00	\$35.00	0.00	\$0.00	Replace	Not Given
		52021471	REINFORCEMENT FRONT	0.00	\$691.10	0.00	\$0.00	Replace	Check
		10	UPPER		,		1	l '	
		52611471	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check
		40	,				1	l '	
		52103470	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		10	,				1	ļ '	
		52102470	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		20						· '	
		52132470	REINFORCEMENT FRONT	0.00	\$238.50	0.00	\$0.00	Replace	Check
		10	LOWER					i i	
		52618470	ABSORBER, FR BUMPER	0.00	\$117.00	0.00	\$0.00	Replace	Check
		90	LOWER						
		53395470	SEAL, HOOD TO FR END	0.00	\$24.40	0.00	\$0.00	Replace	Not Given
		40							
		75310470	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace
		60							
		53112472	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Check
		40							
		53101470	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Check
		80				1			



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 68885592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/08/2022 User ID PohSuan

otal				\$7,551.70		\$2,751.22		
	53202479 01	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given
	53205479 00	SUPPORT S/A UPPER,	0.00	\$364.90	0.00	\$0.00	Replace	Not Given
	81016476 90	HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Not Given
	81145476 91	UNIT , HEADLAMP , RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace
	81210470 20		0.00	\$910.20	0.00	\$0.00	Replace	Not Given
	51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given
	52535500 60	RETAINER, FR BUMPER, LH & RH	0.00	\$8.50	0.00	\$0.00	Replace	Not Given
	52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace

Added Spa	re Parts / N	/laterial Usa	age After Surveyor Signed off						
Part	Portion	Stock	Part Name	Quantity	List Price \$	Discount	Final Price	ARC	Surveyor
Number		Number				(%)	(\$)	Check	Check
Total									

2,751.22 + 200.00 + 230.00 L/S \$2,550/-3,181.22 -20% 2,544.98