

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0545/2022/JT
DATE : 30-Jun-22
WIP : 30769

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR JEREMY KOH JOON KIAT
ADDRESS : BLK 275A BISHAN ST 24
#20-118
SINGAPORE 571275
TELEPHONE : HP +65 97649911
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800015501-04
VEHICLE NO : SLW 4800 T
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 13/2/2018
ENGINE NO : CVK 050345
CHASSIS NO : WAUZZZF43JA072279
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Jun-22
PLACE OF ACCIDENT : 272 BISHAN ST 24

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 4800 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD	S/N \$ 480.00	✓
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	Sac ✓
3	TO RESPRAY FRONT BUMPER.	\$ 900.00	S50 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,622.00	



55 UST ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 4800 T

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>✓ RL R</i>	1	\$	2,377.00	1429.60
2	RADIATOR GRILLE <i>✓ CRA</i>	1	\$	1,478.00	1182.40
3	FRONT BUMPER GRILLE - CENTER <i>X</i>	1	\$	219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>X</i>	1	\$	254.00	
5	FRONT BUMPER FOAM FILLER PIECE <i>? ✓ CRA</i>	1	\$	139.00	110.80
6	FRONT BUMPER REINFORCEMENT BEAM <i>? ✓ BT</i>	1	\$	899.00	719.20
7	FRONT BUMPER TOP COVER <i>? X nn</i>	1	\$	143.00	
8	CAUTION STICKER <i>? X nn</i>	1	\$	16.00	
9	AIR COND STICKER <i>? X nn</i>	1	\$	9.00	
10	FRONT BUMPER BRACKET LOCK CARRIER <i>X NN</i>	1	\$	154.00	
11	FRONT BUMPER SUPPORT - LH / RH <i>? X nn</i>	2	\$	64.00	
12	FRONT BUMPER POP RIVET <i>? ✓ ML</i>	4	\$	4.00	2.88
13	OUTSIDE TEMPERATURE SENSOR BRACKET <i>? ✓ ML</i>	1	\$	21.00	16.32
14	RADIATOR AIR GUIDE INNER - LH / RH <i>? ✓ BR</i>	2	\$	64.00	25.60
15	RADIATOR AIR GUIDE OUTER - LH / RH <i>? X nn</i>	2	\$	28.00	
16	RADIATOR AIR GUIDE UPPER <i>? X NN</i>	1	\$	19.00	
17	FRONT NO PLATE <i>✓ BT</i>	S/N	\$	60.00	60.00
18	SUNDRIES <i>? ✓ nec</i>		\$	250.00	38.96
TOTAL SPARE PARTS			:	\$	6,198.00
TOTAL LABOUR CHARGES			:	\$	2,622.00
GRAND TOTAL			:	\$	8,820.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Eno Q:29

37 days.

Not Authorized. / before print photos

15/7/22

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices on cost, not on inflation
- Third party survey on "without Prejudice" basis
- No illegal practices
- Supplemental survey may be involved and is subject to the Insurance Company

Acknowledged by:

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0545/2022/JT 22-Aug-22 CHANG 1 of 1 SLW 4800 T AUDI A4 SEDAN 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO RESPRAY BONNET.	\$ 900.00	\$ 550.00
GRAND TOTAL		\$ 900.00	\$ 550.00

For Premium Automobiles Pte Ltd

 Authorised Signature