

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0575/2022/EQ
DATE : 13-Jul-22
WIP : 32542

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/07/2022

NTUC Income Insurance Co-Op Ltd

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

OWNER'S NAME : MR CAI ZILIANG
ADDRESS : BLK 469B ADMIRALTY DRIVE
#12-65
SINGAPORE 752469
TELEPHONE : HP +65 94765519
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070125712-01
VEHICLE NO : **SMM 0828 G**
MODEL CODE : A4 2.0 TFSI S TRONIC
MODEL YEAR : 28/8/2020
ENGINE NO : DEM 024299
CHASSIS NO : WAUZZZF49LN015502
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Jul-22
PLACE OF ACCIDENT : VIVO CITY CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMM 0828G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER RADIATOR WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND RADIATOR PARKING. ATD	S/N \$	480.00	/
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	350
3	TO DISMANTLE AND RENEW RADIATOR BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	1,050.00	500
4	TO RESPRAY RADIATOR BUMPER AND RHS RADIATOR FENDER.	\$	2,000.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	/
TOTAL LABOUR CHARGES		:	\$ 4,422.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 0828 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	RADIATOR BUMPER <i>- Cut</i>	1	\$ 2,377.00	
2	RADIATOR BUMPER FIXING PARTS ?	1	\$ 393.00	
3	RADIATOR BUMPER SECURING STRIP ?	1	\$ 40.00	
4	RADIATOR BUMPER GRILLE - CENTER X	1	\$ 219.00	
5	RADIATOR BUMPER CLOSING ELEMENT - LOWER CENTRE X	1	\$ 293.00	
6	RADIATOR BUMPER AIR GUIDE - RH ?	1	\$ 51.00	
7	RADIATOR BUMPER CLOSING ELEMENT - UPPER CENTRE X	1	\$ 293.00	
8	RADIATOR BUMPER AIR GUIDE GRILLE - RH X	1	\$ 151.00	
9	RADIATOR BUMPER TRIM - RH X	1	\$ 54.00	
10	RADIATOR GRILLE X	1	\$ 1,754.00	
11	HORN LOW TONE - RH X	1	\$ 139.00	
12	HORN BRACKET - RH X	1	\$ 33.00	
13	RADIATOR PARKING AID SENSOR X	1	\$ 265.00	
14	RADIATOR PARKING AID SENSOR SEAL RING <i>- M/C</i>	4	\$ 10.00	
15	RADIATOR BUMPER FOAM FILLER PIECE ?	1	\$ 212.00	
16	RADIATOR BUMPER REINFORCEMENT BEAM ?	1	\$ 899.00	
17	RADIATOR GUIDE SECTION - RH ?	1	\$ 41.00	
18	RADIATOR BUMPER TOP COVER X	1	\$ 143.00	
19	"CAUTION" STICKER X	1	\$ 16.00	
20	"A/C" STICKER X	1	\$ 9.00	
SUB TOTAL SPARE PARTS		:	\$ 7,392.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 0828 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LOCK CARRIER BRACKET X	1	\$ 154.00	
22	LOCK CARRIER BRACKET SUPPORT - LH / RH X	2	\$ 64.00	N/V
23	LED HEADLIGHT - RH / Gut	1	\$ 8,172.00	
24	LED HEADLIGHT LIFT CYLINDER - RH X	1	\$ 231.00	
25	LIFT CYLINDER BRACKET - RH X	1	\$ 7.00	NN
26	LIFT CYLINDER HOSE - RH X	1	\$ 107.00	
27	OUTSIDE TEMP SENSOR BRACKET X	1	\$ 21.00	
28	RADIATOR AIR DUCT GUIDE - LH ?	1	\$ 51.00	
29	RADIATOR AIR DUCT GUIDE - RH / UPPER ?	2	\$ 38.00	
30	FRONT WHEEL HOUSING LINER - RH X	1	\$ 262.00	MV
31	FRONT WHEEL SPOILER - RH X	1	\$ 82.00	
32	SUNDRIES ?		\$ 350.00	
TOTAL SPARE PARTS			: \$ 14,784.00	
TOTAL LABOUR CHARGES			: \$ 4,422.00	
GRAND TOTAL			: \$ 19,206.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Que Qiong
3 Days.
Not Authorized. / before paint & photos.
15/7/22

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT