

KAIZEN MOTORS

KAIZEN MOTORS PTE. LTD.

68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896

UEN: 201502816H

GST Reg No. 201502816H

Tel: (+65) 6384 1956

Fax: (+65) 6384 1957

Webpage: <https://www.kaizenmotors.com.sg>



kaizenmotorsingapore



kaizen_motors



kaizenmotors

KNAFX411MJ5755771

Accident Damaged Parts

No	Job Description	Qty	Price / Unit	Amount
1	REAR BOOT <i>nd/but</i>	1	\$ 1,830.00	\$ 1,830.00 ✓
2	REAR BOOT HINGE <i>11</i>	2	\$ 176.00	\$ 352.00 X
3	REAR BOOT HINGE PROTECTOR <i>11</i>	2	\$ 80.00	\$ 160.00 X
4	REAR BOOT HINGE TORSION BAR R/H <i>11</i>	1	\$ 175.00	\$ 175.00 X
5	REAR BOOT HANDLE <i>11</i>	1	\$ 276.00	\$ 276.00 X
6	REAR BOOT KIA LOGO <i>neu</i>	1	\$ 67.00	\$ 44 67.00 ✓
7	REAR BOOT CERATO K3 EMBLEM <i>neu</i>	1	\$ 67.00	\$ 15 67.00 ✓
8	REAR BOOT C&C EMBLEM <i>neu</i>	1	\$ 65.00	\$ 30 65.00 ✓
9	REAR BOOT LOCKING MECHANISM <i>11</i>	1	\$ 354.00	\$ 354.00 X
10	REAR BOOT LOCKING PIN <i>11</i>	1	\$ 90.00	\$ 90.00 X
11	REAR BOOT INNER TRIM <i>11</i>	1	\$ 331.00	\$ 331.00 X
12	REAR BOOT WEATHERSTRIP <i>11</i>	1	\$ 279.00	\$ 279.00 X
13	REAR BOOT LICENSE PLATE LAMP <i>11</i>	2	\$ 65.00	\$ 130.00 X
14	REAR END PANEL TRIM <i>11</i>	1	\$ 467.00	\$ 467.00 ✓
15	REAR END PANEL <i>nd</i>	1	\$ 1,169.00	\$ 1,169.00 ✓
16	REAR SPARE TIRE COMPARTMENT <i>11</i>	1	\$ 1,086.00	\$ 1,086.00 X
17	REAR FENDER <i>11</i>	2	\$ 763.00	\$ 1,526.00 X
18	REAR FENDER INNER TRIM <i>11</i>	2	\$ 655.00	\$ 1,310.00 X
19	REAR FENDER WHEEL GUARD <i>11</i>	2	\$ 533.00	\$ 1,066.00 X
20	REAR TAIL LAMP INNER <i>nd/scre</i>	2	\$ 960.00	\$ 1,920.00 <i>126</i>
21	REAR TAIL LAMP OUTER <i>nd/scre</i>	2	\$ 1,066.00	\$ 2,132.00 <i>126</i>
22	REAR REINFORCEMENT PANEL <i>neu</i>	1	\$ 1,600.00	\$ 318 1,600.00 ✓
23	REAR REINFORCEMENT PANEL SPONGE <i>neu</i>	1	\$ 365.00	\$ 365.00 X
24	REAR BUMPER <i>nd/s</i>	1	\$ 1,073.00	\$ 688 1,073.00 X
25	REAR BUMPER REFLECTOR <i>nd/sra</i>	2	\$ 163.00	\$ 45 326.00 <i>126</i>
26	REAR BUMPER BRACKET <i>11</i>	2	\$ 76.00	\$ 152.00 X
27	REAR BUMPER SKIRTING <i>nd</i>	1	\$ 691.00	\$ 315 691.00 ✓
28	EXHAUST <i>11</i>	1	\$ 1,370.00	\$ 1,370.00 X
29	REAR BOOT INNER TRIM CLIPS <i>11</i>	10	\$ 5.00	\$ 50.00 X
30	REAR FENDER INNER TRIM CLIPS <i>11</i>	20	\$ 5.00	\$ 100.00 X
31	REAR BUMPER CLIPS <i>neu</i>	15	\$ 5.00	\$ 75.00 <i>50</i>
32	REAR EXHAUST TIP <i>11</i>	2	\$ 120.00	\$ 240.00 X
33	REVERSE SENSOR <i>shred</i>	2	\$ 150.00	\$ 300.00 <i>200</i>
34	LICENSE PLATE <i>11</i>	1	\$ 50.00	\$ 50.00 X
35	LICENSE PLATE BRACKET <i>11</i>	1	\$ 50.00	\$ 50.00 X

*no + Auth/1st
dur*

18/7/22

*2/5 & 5100/
6 days*

Date : 15/07/2022

Vehicle No : SMR5993C

Model : KIA Cerato K3

Mileage :

36	LABOUR FOR CHECKING ON WIRING	\$ 250.00	\$ 250.00	20
37	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF REAR END ASSY & PARTS	\$ 3,300.00	\$ 3,300.00	800
38	SPRAYPAINTING & PUTTY OF REAR BUMPER, REAR BOOT REAR DIFFUSER	\$ 2,200.00	\$ 2,200.00	1030
39	LABOUR FOR RETROFITTING MOULDING & SEAL	\$ 550.00	\$ 11 550.00	X
41	WHEEL ALIGNMENT	\$ 150.00	\$ 11 150.00	X

Total \$ 27,744.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-4768

102

9-4291.2

S.N. 250

L-1870

6411.20

202

5128.