

TP China.

SGP9076E. 2009 Dec

Mercedes Benz E200 1796cc

WDD2120482A096503

Front Bumper	Deformed	1455	✓
Front Bumper Clips	Neu	50(SN)	✓
Front Bumper Side Holder x02	Neu	58x2=116.	+
Front Bumper Chrome Moulding x02	Neu	68x2=136.	✓
Front Bumper Sponge RH. Cooled		85	✓
Front Bumper Reinforcement	Neu	628	+
Front Bumper Fog Lamp RH	Cooled	285	✓
Front Bumper Fog Lamp Cover RH.	Neu	91	+
Front Bumper Sensor Pungd		245	✓
Headlamp RH.	Ut	1180	✓

3386

SN: 50

304740.

SGP 9076 E.

Panel Beating

Spray Painting.

Wiring

To remove front bumper sensor

400 350

400 250

680

50. 30

100 50

total: 3777.40

L/S: 3K.

03 Days.

3K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: