

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2200223
Date: 14 Jul 2022

Veh Reg No: SMR4924J
Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
5DR

Chasis No: SJNFEAJ11U1718712

Claim Type: Third Party

Reg. Date: 28/10/2016

Accident Date: 11/07/2022

Your Ref No: SKJ9903C

TP Veh Reg No: SKJ9903C

Estimate Repair Cost to Vehicle No :SMR4924J

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Net Price		
1	1 PC FRT FENDER RH	898.00	
2	1 PC FRT FENDER COWLING RH	311.70	
3	1 PC FRT FENDER ARCH GARNISH RH	594.00	
4	1 PC FRT DOOR RH	1,624.20	
5	2 PCS FRT DOOR HINGE RH	391.80	
6	1 PC FRT DOOR CHECK RH	79.40	
7	1 PC FRT DOOR RUBBER RH	185.00	
8	1 PC FRT DOOR LOWER RUBBER RH	122.00	
9	1 PC FRT DOOR PROTECTOR RH	396.20	
10	1 PC FRT DOOR OUTER CHROME RH	242.00	
11	1 PC FRT RH DOOR BLACK TAPE	58.20	
12	1 PC FRT DOOR FRAME CHROME RH	393.70	
13	1 PC FRT DOOR GLASS REGULATOR ASSEMBLY RH	669.00	
14	1 PC FRT DOOR GLASS CHANNEL RH	271.20	
15	1 PC FRT RH DOOR GLASS CHANNEL PILLAR	199.40	
16	1 PC FRT RH DOOR LOCK	288.00	
17	1 PC FRT RH DOOR LOCK SENSOR	202.10	
18	1 PC FRT RH DOOR LOCK CHECKER	55.40	
19	1 PC FRT DOOR RH TRIM	1,606.00	
20	1 PC REAR DOOR RH	1,512.20	
21	2 PCS REAR DOOR HINGE RH	351.80	
22	1 PC REAR DOOR RH CHECK	66.40	
23	1 PC REAR DOOR RUBBER RH	155.00	
24	1 PC REAR DOOR RH LOWER RUBBER	108.40	
25	1 PC REAR DOOR PROTECTOR RH	368.00	
26	1 PC REAR DOOR OUTER CHROM RH	212.10	
27	1 PC REAR DOOR FRAME CHROM RH	252.20	
28	1 PC REAR DOOR FRAME BLACK TAPE RH	51.40	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2200223
Date: 14 Jul 2022

Veh Reg No: SMR4924J
Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
5DR

Chasis No: SJNFEAJ11U1718712

Claim Type: Third Party

Reg. Date: 28/10/2016

Accident Date: 11/07/2022

Your Ref No: SKJ9903C

TP Veh Reg No: SKJ9903C

Estimate Repair Cost to Vehicle No :SMR4924J

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
29	1 PC REAR DOOR GLASS REGULATOR ASSY RH	581.00	
30	1 PC REAR DOOR GLASS CHANNEL RH	206.20	
31	1 PC REAR DOOR GLASS CHANNEL PILLAR RH	166.90	
32	1 PC REAR DOOR LOCK RH	288.00	
33	1 PC REAR DOOR TRIM RH	2,048.20	
34	1 PC REAR FENDER RH ARCH GARNISH	594.00	
35	1 PC RH DOOR CENTRE PILLAR	1,891.00	
36	1 PC RH DOOR CENTRE PILLAR INNER	644.00	
37	1 PC FRT SHOCK ABSORBER RH	666.00	
38	1 PC FRT SHOCK ABSORBER MOUNTING RH	202.70	
39	1 PC FRT KNUCKLE ARM RH	662.00	
40	1 PC FRT WHEEL HUB RH	388.00	
41	1 PC FRT LOWER ARM RH	288.00	
42	1 PC FRT LOWER ARM BALL JOINT RH	101.40	
43	1 PC ANTI ROLL BAR LINKAGE RH	154.20	
44	1 PC STEERING RACK & PINION	1,778.70	
45	1 PC FRT DRIVE SHAFT RH	1,163.00	
		23,488.10	
		Less 10%	2,348.81
			21,139.29
	Special Net		
46	1 SET FRT FENDER COWLING CLIPS RH	40.00	
47	1 SET FRT FENDER ARCH GARNISH CLIPS	40.00	
48	1 SET FRT DOOR PROTECTOR RH CLIPS	40.00	
49	1 SET FRT DOOR RH LOWER RUBBER CLIPS	40.00	
50	1 SET FRT RH DOOR TRIM CLIPS	40.00	
51	1 SET FRT BUMPER CLIPS	60.00	
52	1 SET REAR DOOR RH RUBBER CLIPS	40.00	
53	1 SET REAR DOOR RH LOWER RUBBER CLIPS	30.00	
54	1 SET REAR DOOR PROTECTOR RH CLIPS	30.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2200223
Date: 14 Jul 2022

Veh Reg No: SMR4924J
Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
5DR

Chasis No: SJNFEAJ11U1718712

Claim Type: Third Party

Reg. Date: 28/10/2016

Accident Date: 11/07/2022

Your Ref No: SKJ9903C

TP Veh Reg No: SKJ9903C

Estimate Repair Cost to Vehicle No :SMR4924J

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
55	1 SET REAR DOOR TRIM CLIPS RH	60.00	
56	1 SET REAR FENDER RH GARNISH CLIPS	40.00	
57	1 SET REAR BUMPER CLIPS	60.00	
58	1 PC FRT SPORTS RIM RH	1,364.10	
59	1 PC FRT TYRE RH	380.00	
		2,264.10	2,264.10
	Labour		
60	1 TO CHECK WIRING	50.00	
61	1 TO REMOVE AND REFIX FRT DOOR GLASS RH	100.00	
62	1 TO REMOVE AND REFIX REAR DOOR GLASS RH	100.00	
63	1 TO REMOVE AND REFIT FRT AND REAR INNER TRIM	200.00	
64	1 TO REMOVE AND REFIT RH SEAT BELT	180.00	
65	1 TO REMOVE AND REFIT SEAT CUSHION	300.00	
66	1 TO REMOVE AND REFIT DASHBOARD	600.00	
67	1 TO REMOVE AND REFIT UNDERCARRIAGE	350.00	
68	1 TO CHECK WHEEL ALIGNMENT	120.00	
69	1 TO SPRAY PANEL SEALANT	180.00	
70	1 TO SPRAY PAINTING	2,000.00	
71	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,800.00	
72	1 TO REFIX UPHOLSTERY	500.00	
		7,480.00	7,480.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/07/2022
TP Veh Reg No: SKJ9903C

Estimate No: EST2200223
Date: 14 Jul 2022

Veh Reg No: SMR4924J
Make/Model: NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD
5DR

Chasis No: SJNFEAJ11U1718712
Reg. Date: 28/10/2016
Your Ref No: SKJ9903C

Estimate Repair Cost to Vehicle No :SMR4924J

Quantity	Description	List Price	Amount
		S\$	S\$
	Total		S\$ 30,883.39
	Add GST @ 7%		2,161.84
	Total Amount Payable		S\$ 33,045.23

TOTAL: SINGAPORE DOLLAR THIRTY THREE THOUSAND FORTY FIVE AND CENTS TWENTY THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE