

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22006775/TQY3Q2**Date:** 29/09/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR003693
Claimant Vehicle No :	SHA7346G	Insured Vehicle No :	SDD9999R
Date of Loss:	14/07/2022	Nature of Claim:	TP
		Claim No:	M2203709

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7346G		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Engine No:	2ZR2C25492
Reg. Date:	31/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU803081178
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,548.13	5,497.41	1,050.72	16.05
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,820.00	1,630.00	1,190.00	42.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,379.13	7,138.41	2,240.72	23.89
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	9,379.13	5,650.00	3,729.13	39.76
+ GST 7.00/7.00% (S\$)	656.53	395.50	261.03	39.76
Nett Amount (S\$)	10,035.66	6,045.50	3,990.16	39.76

INSPECTION

Date of Assignment:	18/07/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	18/07/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA7346G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,303.29 FL	*1,303.29 FL
2	1		*BOOTLID OUTER GARNISH	Cracked	1,054.71 FL	*1,054.71 FL
3	1		*BOOTLID (PRIUS)	Necessary	62.14 FL	*62.14 FL
4	1		*BOOTLID (HYBRID)	Necessary	62.14 FL	*62.14 FL
5	1		*BOOTLID (TOYOTA STAR)	Necessary	81.43 FL	*81.43 FL
6	1		*REAR BUMPER	Deformed	503.40 FL	*503.40 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	378.32 FL	*378.32 FL
8	2		*REAR BUMPER EXTENSION RH/LH	Repair	464.00 FL	*- FL
9	1		*REAR BUMPER LOWER COVER	Deformed	378.32 FL	*378.32 FL
10	10		*REAR BUMPER CLIPS	Necessary	220.00 FL	*22.00 FL
11	1		*REAR BUMPER TOW COVER	Deformed	82.70 FL	*82.70 FL
12	1		*REAR END PANEL	Repair	738.96 FL	*- FL
13	1		*REAR WINDSCREEN GLASS	Necessary	1,758.70 FL	*1,758.70 FL
14	2		*WINDSCREEN SEALANT	Necessary	92.00 F	*92.00 F
15	1		*REVERSE SENSORS	Not Working	135.70 F	*135.70 F
16	1		*BOOTLID (COMFORTDELGRO)	Necessary	30.00 F	*30.00 F
17	1		*BOOTLID (65521111)	Necessary	30.00 F	*30.00 F
18	1		*BOOTLID (APPS)	Necessary	40.00 F	*40.00 F
19	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
20	2		*REAR BUMPER ADVERTISEMENT STICKER RH/LH	Necessary	200.00 F	*200.00 F
21	1		*REAR BUMPER ADVERTISEMENT STICKER	Necessary	50.00 F	*50.00 F
Supplementary #1						
22	1		*BOOTLID LOWER GLASS - BLACK	Necessary	805.80 FL	*805.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,521.61	7,120.65
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,973.48	1,623.24
Total Parts (\$\$)	6,548.13	5,497.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING.	New	1,200.00	700.00
2	SPRAY PAINTING	New	1,200.00	750.00
3	TUFF KOTE	New	100.00	30.00
4	R/I REAR WINDSCREEN GLASSES	New	200.00	120.00
5	R/I REVERSE SENSORS	New	120.00	30.00
Gross Labour Cost (\$\$)			2,820.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >