

ASS. REC. BY: Taufik

REF:

CS/TM/22006775/Tqys**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. M2203709

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Lim TS.

Vehicle: IN / OUT

Veh No: SMA73466 Yr Regn: 2019, May
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FY 80 3081178

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: (Nil) / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wentube

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 18/7/22Survey held at Computer byyDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

02/08/22 @ 3.33pm revised to Ong Chin Klat via Merimen.Taufikh finalised LS \$5650, 3 days. (Red \$3729.13, 40%)

Date/Time, File Pass to?

☐ : Prel. Report1) 22/09 Typist☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Rep. Format: MER-TPLump Sum / L.B.L. 5650

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

CLIS

Singapore

LKK -

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/07/2022
Vehicle Reg. No.:	SHA7346G	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Vehicle Reg. Date:	31/05/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2C25492	Chassis No:	JTDKB3FU803081178
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	5,943.78
Miscellaneous Items	11.00
Labour	2,820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,774.78
+ GST 7.00% (S\$)	614.23
Nett Amount (S\$)	9,389.01

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jul 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA7346G/15/07/2022 14:18

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Llm Tien Siong

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID	25.00	0.00	1,303.29 FL
2	1		*BOOTLID OUTER GARNISH	25.00	0.00	*1,054.71 FL
3	1		*BOOTLID (PRIUS)	25.00	0.00	*62.14 FL
4	1		*BOOTLID (HYBRID)	25.00	0.00	*62.14 FL
5	1		*BOOTLID (TOYOTA STAR)	25.00	0.00	*81.43 FL
6	1		*REAR BUMPER	25.00	0.00	*503.40 FL
7	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	*378.32 FL
8	2		*REAR BUMPER EXTENSION RH/LH	25.00	0.00	*464.00 FL
9	1		*REAR BUMPER LOWER COVER	25.00	0.00	*378.32 FL
10	10		*REAR BUMPER CLIPS	25.00	0.00	*220.00 FL
11	1		*REAR BUMPER TOW COVER	25.00	0.00	*82.70 FL
12	1		*REAR END PANEL	25.00	0.00	*738.96 FL
13	1		*REAR WINDSCREEN GLASS	25.00	0.00	*1,758.70 FL
14	2		*WINDSCREEN SEALANT	0.00	0.00	*92.00 F
15	1		*REVERSE SENSORS	0.00	0.00	*135.70 F
16	1		*BOOTLID (COMFORTDELGRO)	0.00	0.00	*30.00 F
17	1		*BOOTLID (65521111)	0.00	0.00	*30.00 F
18	1		*BOOTLID (APPS)	0.00	0.00	*40.00 F
19	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F
20	2		*REAR BUMPER ADVERTISEMENT STICKER RH/LH	0.00	0.00	*200.00 F
21	1		*REAR BUMPER ADVERTISEMENT STICKER	0.00	0.00	*50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,715.81
- List Item Discount on L Items (\$\$)	1,772.03
Total Parts (\$\$)	5,943.78

ComfortDelGro Engineering Pte Ltd/SHA7346G/15/07/2022 14:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Lim Tien Siong

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING.	New	700	1,200.00
2	SPRAY PAINTING	New	750	1,200.00
3	TUFF KOTE	New	30	100.00
4	R/I REAR WINDSCREEN GLASSES	New	120	200.00
5	R/I REVERSE SENSORS	New	30	120.00
Gross Labour Cost (S\$)				2,820.00

ComfortDelGro Engineering Pte Ltd/SHA7346G/15/07/2022 14:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Jiah 77495749
up' 18/7/22 @ 330 pm
4/5 Resing after repair
3 days
Tan Jiah @ Khantow

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

