

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 19 Jul 2022

Preliminary Advice

Vehicle No : SMV2385G Accident Date : 14/07/2022
Make : MERCEDES-BENZ GLB200 Policy No. :
SP2000525565
Assignment Date : 16/07/2022 Excess : S\$600.00
Date of Inspection : 19/07/2022 Est. Duration of Repair : 4
Inspection At : MBM WHEELPOWER PTE LTD (SIN MING)
176 SIN MING DRIVE #01-15, SIN MING AUTOCARE
SINGAPORE 575721

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 22,463.80
Revised Amount	:S\$ 3,686.40
Check Items (Estimated)	:S\$ 7,882.00
Total	:S\$ 11,568.40
Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 188,000.00
COE / PARF Rebate	:S\$ 64,109.00
Salvage Value	:S\$

Margin for Repair

:S\$ 123,891.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.