



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0068864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

Allianz Insurance Singapore Pte. Ltd. (HQ)

CK146001

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	08/07/2022
Policy No:		Date of Loss:	
Vehicle Reg. No.:	SKB7431C	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HONDA CIVIC, 1.8 L 5AT (A)	Vehicle Reg. Date:	30/06/2009
Vehicle Colour:	WHITE	Chassis No:	JHMF16309S202184
Engine No:	R18A14013273		
Odometer:	0 KM		
Paint Type:	NO		
Total Loss?	18		
Est. Duration of Repair (day)			
Present Location:	MOVA AUTOMOTIVE PTE LTD (15 FAN YOONG)		

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	10,626.95
Labour	0.00
Paintwork Labour	5,320.00
Towing	0.00
Gross Total (\$\$)	15,946.95
+ GST 7.00% (\$\$)	1,116.29
Nett Amount (\$\$)	17,063.24

This claim is handled by: BRIAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Estimate Report

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 15 Jul 2022)

Parts: 143

HONDA CIVIC 1.8 L 5AT (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKB7431C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR WINDSCREEN / BR	0.00	0.00	*480.00 F
2	1		*REAR WINDSCREEN SEAL / nec	0.00	0.00	*45.50 F
3	1		*REAR BOOT LID / on	0.00	0.00	*455.00 F
4	1		*REAR BOOT LID SEAL / CR4	0.00	0.00	*52.00 F
5	2		*REAR BOOT LID HINGE LH & RH / RT	0.00	0.00	*100.00 F
6	2		*REAR BOOT LID HINGE COVER LH & RH / CR4	0.00	0.00	*36.00 F
7	1		*REAR BOOT LID INNER TRIM / CR4	0.00	0.00	*100.00 F
8	10		*REAR BOOT LID INNER TRIM CLIPS / nec	0.00	0.00	*20.00 F
9	1		*HONDA LOGO / BR	0.00	0.00	*18.00 F
10	1		*REAR BOOT LID OUTER TRIM / BR	0.00	0.00	*40.00 F
11	2		*NUMBER PLATE LAMP / BR	0.00	0.00	*40.00 F
12	1		*REVERSE CAMERA / X AN	0.00	0.00	*280.00 F
13	1		*BOOT LID LOCK / RT	0.00	0.00	*95.50 F
14	2		*REAR FENDER LH & RH / on	0.00	0.00	*500.00 F
15	2		*REAR FENDER INNER LH & RH / X RR / MU	0.00	0.00	*700.00 F
16	20		*REAR FENDER INNER CLIPS / nec	0.00	0.00	*60.00 F
17	2		*TAILLAMP PANEL LH & RH / on	0.00	0.00	*179.00 F
18	4		*TAILLAMP MOUNTING CLIPS HOLDER / ms	0.00	0.00	*12.00 F
19	1		*VENTILATION FLAP / OR	0.00	0.00	*35.00 F
20	2		*TAILLAMP INNER LH & RH / BR	0.00	0.00	*300.00 F
21	2		*TAILLAMP OUTER LH & RH / BR	0.00	0.00	*600.00 F
22	1		*REAR BUMPER / BR	0.00	0.00	*250.00 F
23	2		*REAR BUMPER RETAINER LH & RH / OR	0.00	0.00	*40.00 F
24	10		*REAR BUMPER CLIPS / nec	0.00	0.00	*15.00 F
25	2		*MUDFLAP LH & RH / OR	0.00	0.00	*100.00 F
26	1		*REAR BUMPER LOWER 71504SNB000 / BR	0.00	0.00	*18.50 F
27	2		*EXHAUST TAILPIPE CHROME COVER / X AN	0.00	0.00	*178.00 F
28	1		*EXHAUST SILENCER HEAT INSULATOR / X M	0.00	0.00	*45.00 F
29	1		*REAR END PANEL / on	0.00	0.00	*250.00 F
30	1		*REAR BOOT FLOOR / X R	0.00	0.00	*800.00 F
31	1		*REAR END PANEL TOP COVER / CR4	0.00	0.00	*220.00 F
32	1		*SPEAKER BOARD / CR4	0.00	0.00	*220.00 F
33	1		*SPARE TYRE BOARD / COVER / X M	0.00	0.00	*200.00 F
34	2		*LUGGAGE COMPARTMENT INNER TRIM LH/RH / CR4	0.00	0.00	*310.00 F
35	20		*LUGGAGE COMPARTMENT INNER TRIM CLIPS / nec	0.00	0.00	*40.00 F
36	1		*REAR CHASSIS MEMBER 656660SNLZ01ZZ / X R / DD	0.00	0.00	*390.00 F
37	1		*ROOF LINING / TH	0.00	0.00	*950.00 F
38	1		*REVERSE SENSOR / BR	200/-	0	*250.00 F
39	1		*SOLAR FILM / nec	200/-	0	*300.00 FS
40	1		*WINDSCREEN PRIMER / nec	30/-	0	*40.00 FS
41	1		*WINDSCREEN SEALANT / nec	0	0.00	*40.00 FS
42	1		*HELLA DASH CAM / X M	0	0.00	*450.00 FS
43	1		*FUEL CAP LOGO WRITING / X M	0	0.00	*120.00 FS
44	1		*REAR BUMPER LOGO / M	0	0.00	*150.00 FS
45	1		*LH REAR TYRE 225/40R18 / M	0	0.00	*285.00 FS
Sub Total (S\$)						9,809.50
+ Margin on L,N Items 10.00% (S\$)						817.45
Total Parts (S\$)						10,626.95

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS6131.50
+ 10%
6744.65

819.50 nett

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimate Report

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO CUT/ KNOCK / WELDING LH & RH REAR FENDER, TAILLAMP PANEL LH & RH, REAR END PANEL & BOOT FLOOR & LH CHASSIS MEMBER. TO REALIGN ALL THE CONNECTION & REPLACE DAMAGED PARTS	New 1800 /	2,200.00
2	TO SPRAY PAINT ON LH REAR DOOR, LH & RH REAR FENDER, REAR BOOT LID, TAILLAMP PANEL LH & RH, REAR BOOT FLOOR, REAR END PANEL, CHASSIS MEMBER & REAR BUMPER	New 1400 /	2,100.00
3	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS	New 30 /	50.00
4	TO APPLY BODY SEALANT ON CUTTING AREAS	New 30 /	80.00
5	TO REPLACE REAR WINDSCREEN	New	120.00
6	TO REMOVE & REFIT REAR COMPARTMENT UPHOSTERY, SIDE TRIM / COVERING, INNER TRIM TO ASSIST REPAIR	New 80 /	180.00
7	TO REALIGN CHASSIS ALIGNMENT	New 200 /	350.00
8	TO INSTALL REVERSE SENSOR & CHECK FUNCTIONING	New 30 /	40.00
9	TO INSTALL REVERSE CAMERA & SETTING UP HEAD UNITS	New 30 /	80.00
10	TO CONDUCT WIRING CHECK / DIAGNOSE & RESET SYSTEM AFTER REPAIR	New 30 /	120.00

Gross Labour Cost (S\$)

5,320.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3750

Steve (LKK)
18/7/12, 1.17p

W N
LIS
by ALy
14 Lys

= 11,314.15

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 18 Sep 2022)**Parts:** 143 HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Mova Automotive Pte Ltd/SKB7431C/18/09/2022 14:31**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT FLOOR SIDE PANEL,LH	0.00	0.00 BT	*185.00 F ✓
2	1		*CHASSIS EXTENSION/END CAP LH	0.00	0.00 BT	*65.00 F ✓
3	1		*LH WHEEL HOUSE SUB PANEL	0.00	0.00 BT	*175.00 F ✓
			Sub Total (\$\$)			425.00
			+ Margin on L,N Items 10.00% (\$\$)			42.50
			Total Parts (\$\$)			467.50 ✓

F=Franchise part.

Mova Automotive Pte Ltd/SKB7431C/18/09/2022 14:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BODY JOINT SEALANT	50.00 40 ✓
Sub Total (S\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CUT /WELD /KNOCKING & REPLACE ABOVE ITEMS	New	200 ✓ 500.00 400
2	TO SPRAY PAINT ON ABOVE ABOVE ITEMS	New	✗ 450.00 400
Gross Labour Cost (S\$)			950.00

Mova Automotive Pte Ltd/SKB7431C/18/09/2022 14:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

supp total - 707.50

Main estimate - 11,314.15

12,021.65

L/S - 9617.32
= 9600

P: 467.50

S/N: 40

L: 800

Total : 1307.50

Supplementary