

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobiles 3/ASM22000967/Vcy3-1						
	AXA INSURANCE			Ref:	C20///CIVIZZ000301/VCy3	
	8 SHENTON WAY AXA TOWERSING			Date:	22/01/2022	
				Code:	ASM	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 9841E	Veh. Inspected	k	SMX 3854C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M03RTC	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		22/01/2022	
2.	Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	22/01/2022	Inspection Dat	e		
	Survey held at	TEAMWORK GARAGE PTE LTD)			
		53 UBI AVENUE 1 #01-24 SINGAPORE 408934.				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					