



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22003300/Vqy3e2-1	
			Date: 20/07/2022	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBH 1561A	Veh. Inspected	SKX 8347R
	Policy No.	Z22VC05009838	Coverage (\$)	0.00
	Claim No.	22/22/22VC05/025643	Excess (\$)	0.00
	Assign From	KENNY LIM	Assign Date	09/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	B.M.W. 216D	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WBA2B32090V259765	Colour	BROWN
	Odometer	198255 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	BRIDGESTONE	7 mm
	L/H Front Tyre	205/55 R16	BRIDGESTONE	7 mm
	R/H Rear Tyre	205/55 R16	BRIDGESTONE	7 mm
	L/H Rear Tyre	205/55 R16	BRIDGESTONE	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/04/2022	Inspection Date	13/04/2022
	Survey held at	CHNG BROTHER MOTOR SERVICE 2 KAKI BUKIT AVENUE 2 #02-32 KAKI BUKIT AUTOHUB SINGAPORE 417921.		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	