



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/LPC22003300/Vqy3-1

LONPAC INSURANCE BHD

300 BEACH ROAD #17-04/07 THE CONCOURSE
SINGAPORE 199555

Ref: ~~000/LPC22000000/Vqy002~~

Date: ~~11/05/2022~~ 09/05/2022

Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBH 1561A	Veh. Inspected	SKX 8347R
Policy No.	Z22VC05009838	Coverage (\$)	0.00
Claim No.	22/22/22VC05/025643	Excess (\$)	0.00
Assign From	GERALD POH KENNY LIM	Assign Date	11/04/2022 09/05/2022

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 216D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA2B32090V259765	Colour	BROWN
Odometer	198255 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	BRIDGESTONE	7 mm
L/H Front Tyre	205/55R16	BRIDGESTONE	7 mm
R/H Rear Tyre	205/55R16	BRIDGESTONE	7 mm
L/H Rear Tyre	205/55R16	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
--

5. General Information

Accident Date	04/04/2022	Inspection Date	13/04/2022
Survey held at	CHNG BROTHER MOTOR SERVICE 2 KAKI BUKIT AVENUE 2 #02-32 KAKI BUKIT AUTOHUB SINGAPORE 417921.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--