

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006792/ECY3M4**Date:** 21/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00153032100

**Claimant Vehicle
No :** SNC5653B**Insured Vehicle
No :** GBL6225S

Date of Loss: 07/07/2022

Nature of Claim: TP

Claim
No: SNM22D204891/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNC5653B**

Make & Model: VOLVO S60, 2.0 B4 RD (A)

Engine No: B420T64150298

Reg. Date: 28/10/2021 (Man. Year: 2021)

Chassis No: 7JRZSK9TDNG156171

Colour: Grey

Odometer: 3611 km

Engine Capacity: 1969 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,810.30	13,210.92	2,599.38	16.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,960.00	720.00	26.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,490.30	15,170.92	3,319.38	17.95
+ GST 7.00/7.00% (S\$)	1,294.32	1,061.96	232.36	17.95
Nett Amount (S\$)	19,784.62	16,232.88	3,551.74	17.95

INSPECTION

Date of Assignment: 18/07/2022

Date Inspected: 19/07/2022

Inspected At: ETHOZ GROUP LTD
30 BUKIT BATOK CRESCENT
SINGAPORE 658075

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2022)
Parts:	143	VOLVO S60 2.0 B4 RD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC5653B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	2,660.00 FL	*2,660.00 FL
2	1		*REAR BUMPER LOWER	Crushed	672.00 FL	*672.00 FL
3	1		*REAR BUMPER RETAINER RH	Not Necessary	105.00 FL	*- FL
4	1		*REAR BUMPER TOW COVER RH	Missing	196.00 FL	*168.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	490.00 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	100.00 FL	*30.00 FL
7	1		*REAR BUMPER REFLECTOR RH	Cracked	196.00 FL	*176.40 FL
8	1		*BOOT LID	Dented	4,680.00 FL	*4,100.00 FL
9	1		*EMBLEM - VOLVO	Necessary	210.00 FL	*189.00 FL
10	1		*EMBLEM - B4	Necessary	196.00 FL	*176.40 FL
11	1		*EMBLEM - S60	Necessary	210.00 FL	*189.00 FL
12	1		*BOOT LID LAMP RH	Not Necessary	672.00 FL	*- FL
13	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
14	1		*REAR DOOR RH	Dented	4,060.00 FL	*3,350.00 FL
15	1		*REAR DOOR OUTER HANDLE RH (NPA)	Repair	0.00 FL	*- FL
16	1		*REAR SPORTS RIM RH	Cut	2,600.00 FL	*2,500.00 FL
17	1		*REAR DOOR WEATHERSTRIP RH	Necessary	520.00 FL	*468.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	17,567.00	14,678.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,756.70	1,467.88
Total Parts (\$\$)	15,810.30	13,210.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,200.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,200.00	1,000.00
3	TO RENEW AND BALANCE REAR RIM	New	100.00	80.00
4	TO TRANSFER REAR BOOT LID COMPONENTS	New	150.00	50.00
5	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (\$)			2,680.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >