

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 30 BUKIT BATOK  
CRESCENT (S 658075)

Selamatshahh  
CLAIM DEPARTMENT  
DID : 66547519  
FAX :

Date : 14/07/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 07/07/2022

Vehicle No : SNC-5653-B

Make & Model : VOLVO S60 B4 R-DESIGN 2.0 (A)

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY              | DESCRIPTION                     | REPAIRER AMT (\$) | SURVEYOR APP.       |
|------------------|---------------------------------|-------------------|---------------------|
| <b>List Item</b> |                                 |                   |                     |
| 1                | REAR BUMPER / BR                | ✓ 2,660.00        | <del>2394</del>     |
| 1                | REAR BUMPER LOWER / CR4         | ✓ 672.00          | <del>604.80</del>   |
| 1                | REAR BUMPER RETAINER RH ? X m   | 105.00            |                     |
| 1                | REAR BUMPER TOW COVER RH / m/s  | 196.00            | <del>80</del> 168 ✓ |
| 1                | REAR BUMPER REINFORCEMENT ? X m | 490.00            |                     |
| 10               | REAR BUMPER CLIPS / m/c         | 30 ✓ 100.00       |                     |
| 1                | REAR BUMPER REFLECTOR RH / CRA  | 196.00            | 176.40 ✓            |
| 1                | BOOT LID / 00                   | 4100 ✓ 4,680.00   | <del>4212</del>     |
| 1                | EMBLEM - VOLVO / m/c            | 210.00            | 189 ✓               |

PAGE : 1

Date : 14/07/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 07/07/2022

Vehicle No : SNC-5653-B

Make & Model : VOLVO S60 B4 R-DESIGN 2.0 (A)

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

| QTY                   | DESCRIPTION                   | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----------------------|-------------------------------|-------------------|---------------|
| 1                     | EMBLEM - B4 / 1k              | 196.00            | 176.40 /      |
| 1                     | EMBLEM - S60 / 1k             | 210.00            | 189 /         |
| 1                     | BOOT LID LAMP RH X 111        | 672.00            |               |
| 1                     | REAR FENDER RH X R            | RESTORE           |               |
| 1                     | REAR DOOR RH / 00             | RESTORE \$4060    | 3354 / 3350 ✓ |
| 1                     | REAR DOOR OUTER HANDLE RH X R | RESTORE           |               |
| 1                     | REAR SPORTS RIM RH / 07       | 2,600.00          | 2340 / 2500 ✓ |
| Sub Total             |                               | 12987.00          |               |
| Discount 10% On Parts |                               | (1298.70)         |               |
| Labour & Misc         |                               | 14,210.80         | 14,045.60     |
|                       |                               | -10%              | -10%          |
|                       |                               | 12,789.72         | 12,641.04     |

Date : 14/07/2022  
 To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
 ESTIMATION  
 Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd  
 : SOMPO INSURANCE SINGAPORE PTE. LTD.  
 Certificate No : 1 Accident Date : 07/07/2022  
 Vehicle No : SNC-5653-B Make & Model : VOLVO S60 B4 R-DESIGN 2.0 (A)

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                                  | REPAIRER AMT (\$)         | SURVEYOR APP.              |
|-----|----------------------------------------------|---------------------------|----------------------------|
|     | LABOUR TO FACILITATE REPAIR                  | 1,200.00                  | 800                        |
|     | TO RESPRAY AFFECTED AREAS                    | 1,200.00                  | 1000                       |
|     | TO RENEW AND BALANCE REAR RIM (11/11/21)     | 100.00                    | 3080                       |
|     | TO TRANSFER REAR BOOT LID COMPONENTS         | 150.00                    | 50                         |
|     | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS | 30.00                     | /                          |
|     | Sub Total                                    | 2680.00                   | 1960                       |
|     |                                              |                           | = 14,749.72 + 15,077.24    |
|     |                                              | 14,749.72 + Supp - 421.20 |                            |
|     |                                              | 14,368.30                 |                            |
|     |                                              |                           | part by part - \$15,170.92 |
|     |                                              | SUB TOTAL                 |                            |
|     |                                              | GST 7.0 %                 | 1,005.78                   |
|     |                                              | TOTAL                     | 15,374.08                  |

Remarks: LKZ Auto Consultants hence notify the Repairer of the following:  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary work(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Surveyor's name:

Principal's name: ETHOZ Group Ltd

Survey Date & Time: