

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

MV-1851

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.F. (\$) _____

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

Veh No: SNC5653B Yr Regn: 28/19/21Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Vaux S60 c.c. 1969Colour: Grey A/C: ☐ Insured / ☐ Std / ☐ HI / ☐ NASp. Reading: 3611 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: 15R2SK9TONGK56171Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 1BS / DUN / EXNOVA / GY / FS / LIZA / ☒ TOYO / YOKO or

TOYO / YOKO or

Front: 4 mmR/Bal. 4 mmL/Bal. 4 mmD.O.A. 7/7/22 Ethoz

Survey held at _____

Des. of Damages: Frt / Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision.

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 14/07/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1 Accident Date : 07/07/2022
Vehicle No : SNC-5653-B Make & Model : VOLVO S60 B4 R-DESIGN 2.0 (A)

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	REAR BUMPER / DR	2,660.00	
1	REAR BUMPER LOWER / CR4	672.00	
1	REAR BUMPER RETAINER RH ?	105.00	
1	REAR BUMPER TOW COVER RH - mis	196.00	
1	REAR BUMPER REINFORCEMENT ?	490.00	
10	REAR BUMPER CLIPS / n/c	100.00	
1	REAR BUMPER REFLECTOR RH - CR4	196.00	
1	BOOT LID / DR	4,680.00	
1	EMBLEM - VOLVO - n/c	210.00	

Date : 14/07/2022

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 07/07/2022

Vehicle No : SNC-5653-B

Make & Model : VOLVO S60 B4 R-DESIGN 2.0 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	EMBLEM - B4 / nk	196.00	
1	EMBLEM - S60 / nk	210.00	
1	BOOT LID LAMP RH X	672.00	
1	REAR FENDER RH X R	RESTORE	
1	REAR DOOR RH / 00	RESTORE \$	
1	REAR DOOR OUTER HANDLE RH X R	RESTORE	
1	REAR SPORTS RIM RH / 07	2,600.00	
	Sub Total	12987.00	
	Discount 10% On Parts	(1298.70)	
	<u>Labour & Misc</u>		

Date : 14/07/2022
 To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION
 Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : 1 Accident Date : 07/07/2022
 Vehicle No : SNC-5653-B Make & Model : VOLVO S60 B4 R-DESIGN 2.0 (A)

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	LABOUR TO FACILITATE REPAIR	1,200.00	800
	TO RESPRAY AFFECTED AREAS	1,200.00	1000
	TO RENEW AND BALANCE REAR RIM (Alignment)	100.00	300
	TO TRANSFER REAR BOOT LID COMPONENTS	150.00	50
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	/
	Sub Total	2680.00	

Stere (LKK) W PL
 19/7/22, 10.00 P/P
 6 dy

LKK Auto Consultants hence notify the Repairer of the following:
 Remarks:
 • To survey before/after spray painting
 • To survey damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary details may be required and is subject to final approval from insurance Company

14,368.30

SUB TOTAL
GST 7.0 % 1,005.78
TOTAL 15,374.08

Acknowledged by Repairer

Signature:

Surveyor's name:

Principal's name: ETHOZ Group Ltd

Survey Date & Time: