

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 20006262D

ceville

not Authorised
 19/7/22
 2/506000/
 4 days.

VEHICLE No: SMR 7074S

1PC	REAR BUMPER	DIS	1615.00	\$1,685.00 /
1PC	REAR BUMPER LOWER	DIS	828.00	\$981.00 /
1PC	REAR BUMPER DIFFUSER	NF		\$650.00 X
1PC	REAR BUMPER BEAM	Bent	850.00	\$982.00 /
1P	REAR BUMPER REFLECTOR N/S	11		\$150.00 X
1PC	REAR BUMPER PDC SENSOR N/S	shock		\$182.00 /
1SET	REAR BUMPER CLIPS	11		\$50.00 /
1PC	REAR AIR VENT N/S	11		\$112.00 X
1PC	TAILLAMP N/S	520	458.00	\$820.00 /
1PC	REAR END PANEL	R		\$998.00 X
1PC	REAR FENDER N/S	m/megat	1822.00	\$2,455.00 /
1PC	REAR SHOCK ABSORBER N/S	11		\$390.00 X
1PC	REAR WHEEL HUB BEARING N/S	11		\$850.00 X
1PC	REAR SPORT RIM N/S	warp		\$1,200.00 600 S/W
				\$11,505.00

102

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00 50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00 80
TO DISMANTLE & REFIX REAR UNDER CARRIAGE	11 \$180.00 X
TO CONDUCT WHEEL ALIGNMENT	\$120.00 60
TO SPRAY RUST PROOFING	\$80.00 30
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00 700
TO PUTTY & SPRAY PAINTING	\$1,500.00 800
TOTAL	\$14,835.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P. 5805
 102
 522450
 600
 1740
 7564.5
 206
 6057