



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref:	CS3/CTI22006795/Gqy3
3 ANSON ROAD #16-00		Date:	18/07/2022
SPRINGLEAF TOWERSINGAPORE 079909		Code:	CTI
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLM 3983H	Veh. Inspected	FBT 4505E
Policy No.		Coverage (\$)	0.00
Claim No.	SNM22D204844/C02/SLM3983 H/THAMYL	Excess (\$)	0.00
Assign From	PAULINE THAM	Assign Date	18/07/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/07/2022	Inspection Date	18/07/2022
Survey held at	25 KAKI BUKIT ROAD 4, #01-28, SYNERGY @ KB		
Repairer	BIKES AND TEA PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			