



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERS SINGAPORE 048623

Ref: CS3/SMO22006797/Kvy3

Date: 18/07/2022

Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLU 8881T	Veh. Inspected	SFJ 418E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2202435/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	18/07/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	15/07/2022	Inspection Date	19/07/2022
Survey held at	8 PARAGON PTE LTD 71 WOODLANDS AVENUE 10, #01-10, WOODLANDS INDUSTRIAL XCHANGE, SINGAPORE 737743		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.