

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/LPC22006798/49a3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMD9053M

at Workshop m/s

10th Nov 18

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$82k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

1.3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

778x

Date:

Person Contacted:

17A 36416

Vehicle: IN / OUT

Date / Time

Action / Instruction

27/11/18

Veh No:

SMD9053M

Regn:

11/09/18

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Honda HR-V

c.c

1496

Colour

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

36701

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRU1830JX200259

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

16/07/22

D.O.I.

26/7/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

29/8/22 PIP # 10242-32 insured to soon



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT22002037	Page	1
Registration No	: SMD9053M	Date	: 18. Jul 2022	Customer No.	: WZL009
Chassis No	: JHMRU1830JX200259	Svc Advisor	: YOU PO SOON	Engine No	: L15B5670259
Model	: HRV LX-SIN CVT YM 2018	Date Time	: 18. Jul 2022 3:36:48 PM	Surveyor Name	:
Owner's Name	: VAKULABHARANAM SANTHI	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 16/7/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: MS SANTHI OWNER INSURER: SINGLIFE ACC DATE: 16/7/2022 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: SKX4072J						
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>rec</i>	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 <i>rec</i>	1	9.10	25	6.82	0.48	7.30
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>rec</i>	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT <i>nn</i>	1	5.20	25	X 3.90	0.27	4.17
91501-S70-003	FASTENER BW/SHIELD <i>rec</i>	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B <i>rec</i>	2	5.50	25	8.25	0.58	8.83
91536-SS0-J01	FASTENER AW/SHIELD <i>rec</i>	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>rec</i>	21	60.00		1260.00	8.40	128.40
68100-T7A-J20ZZ	TAIL GATE COMP <i>body</i>	1	912.60	25	684.45	47.91	732.36
84441-S2K-000ZB	POCKETTAILGATE PULL <i>11</i>	1	16.20	X 25	12.15	0.85	13.00
84431-T7A-J01ZA	LINING ASSYTAILGATE <i>11</i>	1	145.10	X 25	108.82	7.62	116.44
74440-T7A-003	WEATHERSTRIPTAILGATE <i>70.1</i>	1	105.20	25	78.90	5.52	84.42
74800-T7Y-K01	LOCK ASSY,TAILGATE ASSY <i>su</i>	1	174.00	X 25	130.50	9.14	139.64
75722-T7W-A01	EMBLEMRR. <i>rec</i>	1	15.20	25	11.40	0.80	12.20
75725-T8N-T00	EMBLEM,RR. I-VTEC <i>rec</i>	1	16.60	25	12.45	0.87	13.32
75701-T4G-000	EMBLEM <i>rec</i>	1	25.80	25	19.35	1.35	20.70
90301-ST0-003	NUT,PUSH 3MM <i>rec</i>	2	2.10	25	3.15	0.22	3.37
34150-T7A-J31	LIGHT ASSY,R.LID <i>11</i>	1	287.80	X 25	215.85	15.11	230.96
34155-T7A-J31	LIGHT ASSY,L.LID <i>11</i>	1	287.80	X 25	215.85	15.11	230.96

Printed on 18/7/2022 4:28:38 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMD9053M
Chassis No : JHMRU1830JX200259
Model : HRV LX-SIN CVT YM 2018
Owner's Name : VAKULABHARANAM SANTHI
Ins Policy No. :
Date of Accident : 16/7/2022

Document No. : SQT22002037 **Page** 2
Date : 18. Jul 2022
Customer No. : WZL009
Svc Advisor : YOU PO SOON
Engine No : L15B5670259
Date | Time : 18. Jul 2022 3:36:48 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
33502-T7A-J31	LAMP UNIT,R. 17	1	428.30	25	321.22	22.49	343.71	
33552-T7A-J31	LAMP UNIT,L. 17	1	428.30	25	321.22	22.49	343.71	
74940-TZ5-A01	BUZZER ASSYSMART 17	1	64.50	25	48.37	3.39	51.76	
38387-TZ5-A01	ANTENNA ASSYL.F. 17	1	63.20	25	47.40	3.32	50.72	
04715-T7A-900ZZ	FACE,RR.BUMPER 17	1	492.50	25	369.37	25.86	395.23	
04717-T7A-J00ZZ	FACE,R.RR.BUMPER CORNER 17	1	100.40	25	75.30	5.27	80.57	
04718-T7A-J00ZZ	FACE,L.RR.BUMPER CORNER 17	1	100.40	25	75.30	5.27	80.57	
91505-TM8-003	CLIP,BUMPER 17	8	2.30	25	13.80	0.97	14.77	
66100-T7A-300ZZ	PANEL COMPRR. 17	1	397.90	25	298.42	20.89	319.31	
84640-T7A-J01ZA	LINING ASSYRR.PANEL 17	1	46.80	25	35.10	2.46	37.56	
04655-T7A-310ZZ	PANEL SET,RR.FLOOR 17	1	720.30	25	540.22	37.82	578.04	
65513-T7A-300ZZ	STIFFENERRR.JACK UP 17	1	65.50	25	49.12	3.44	52.56	
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR 17	1	95.50	25	71.62	5.01	76.63	
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR 17	1	320.00		320.00	22.40	342.40	
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) 17	1	45.00		45.00	3.15	48.15	
72841-SH3-315	OILSHEET 17	1	43.40	25	32.55	2.28	34.83	
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR 17	1	210.50	25	157.87	11.05	168.92	
84550-T7A-J10	BOX ASSY,CARGO FL 17	1	138.10	25	103.57	7.25	110.82	
2 pcs Reel under sole protector L.H & R.H 17					Sum Item	4607.83	322.57	4,930.40
BOSUN	SUNDRIES 17	1	50.00	20	50.00	3.50	53.50	
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER 17	1	180.00	120	180.00	12.60	192.60	
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N) 17	1	200.00	150	200.00	14.00	214.00	
BOJSE	BODY JOINT SEALANT. 17	1	300.00	100	300.00	21.00	321.00	
BOBC	BODY UNDERSIDE COATING (N) 17	1	200.00	100	200.00	14.00	214.00	
BP00R	APPLY BODY UNDERSIDE COATING (N). 17	1	480.00	180	480.00	33.60	513.60	
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS 17	1	520.00	325	520.00	36.40	556.40	
BC012R	RESET VEHICLE SMART ENTRY SYSTEM 17	1	480.00	350	480.00	33.60	513.60	
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA 17	1	480.00	350	480.00	33.60	513.60	

Printed on 18/7/2022 4:28:38 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMD9053M
Chassis No : JHMRU1830JX200259
Model : HRV LX-SIN CVT YM 2018
Owner's Name : VAKULABHARANAM SANTHI
Ins Policy No. :
Date of Accident : 16/7/2022

Document No. : SQT22002037 **Page** 3
Date : 18. Jul 2022
Customer No. : WZL009
Svc Advisor : YOU PO SOON
Engine No : L15B5670259
Date | Time : 18. Jul 2022 3:36:48 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	480.00	11 X	480.00	33.60	513.60
BMU30R	REMOVE & INSTALL EXHAUST SYSTEM.(N)	1	480.00	11 X	480.00	33.60	513.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	480.00	11 X	480.00	33.60	513.60
BMI02D	REMOVE & INSTALL RR SEATS LININGS GARNISHES & ETC	1	520.00	11 X	520.00	36.40	556.40
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	450	650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	✓	650.00	45.50	695.50
BKRP02B	CUT & RENEW RR FLOOR PANEL. STRAIGHTEN FENDERS ALIG	1	5500.00	2600	5500.00	385.00	5885.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	3800.00	2600	3800.00	266.00	4066.00
Sum Labor					15450.00	1,081.50	16,531.50

Survey By: Marcus Loh
Date & Time: 26/07/22 @ 3pm
Excess:
Status: not Allowed
Signature: Take photo before repairing
7 days

Total Amount 20,057.83 1,404.07 21,461.90
Total (Inclusive of GST) 21,461.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 18/7/2022 4:28:38 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT22002457	Page	1
Registration No	: SMD9053M	Date	: 24. Aug 2022		
Chassis No	: JHMRU1830JX200259	Customer No.	: WZL009		
Model	: HRV LX-SIN CVT YM 2018	Svc Advisor	:		
Owner's Name	: VAKULABHARANAM SANTHI	Engine No	: L15B5670259		
Ins Policy No.	:	Date Time	: 24. Aug 2022 5:23:50 PM		
Date of Accident	:	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	SUPPLEMENTARY						
74410-T7A-J01ZD	PROTECTORRR.RR.WHEEL ARCH	1	187.90	25	140.92	9.86	150.78
74450-T7A-J01ZP	PROTECTOR L,RR.	1	180.60	25	134.92	9.48	144.93
					Sum Item	276.37	19.34
							295.71

Survey By

Date & Time

Excess

Status

Signature

Total Amount 276.37 19.34 295.71

Total (Inclusive of GST) 295.71

Printed on 24/8/2022 5:24:35 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.