



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22006806/Uqy3m4	
			Date: 15/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 5283G	Veh. Inspected	FBJ 8177U	
Policy No.	D22MTPCVE000345	Coverage (\$)	0.00	
Claim No.	CMTD2202433/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	18/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	KYMC0 K-XCT200I	c.c	199	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	RFBD82000E1000177	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70-14	TIMSUN	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	150/70-13	TIMSUN	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/07/2022	Inspection Date	01/08/2022	
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	