

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0591/2022/EQ  
DATE : 16-Jul-22  
WIP : 33072

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/07/2022**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

OWNER'S NAME : MR LEE CHOON KIAT  
ADDRESS : BLK 427 SERANGOON CENTRAL  
#05-300  
SINGAPORE 550427  
TELEPHONE : HP +65 9616 1026  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1800039936-04  
VEHICLE NO : SFV 5188 Y  
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI  
MODEL YEAR : 23/4/2018  
ENGINE NO : CVK 057988  
CHASSIS NO : WAUZZZF44JA139441  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 14-Jul-22  
PLACE OF ACCIDENT : DEFU LANE 10



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFV 5188 Y**

| S/N                            | NATURE OF JOBS                                                                   | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|--------------------------------|----------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                              | TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR.                   | S/N \$ 360.00        | /                          |
| 2                              | TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER. | S/N \$ 600.00        | /                          |
| 3                              | TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.                                  | S/N \$ 200.00        | 150                        |
| 4                              | TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES.                              | S/N \$ 400.00        | /                          |
| 5                              | TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.                                   | S/N \$ 800.00        | ?                          |
| <b>SUBTOTAL LABOUR CHARGES</b> |                                                                                  | <b>: \$ 2,360.00</b> |                            |



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFV 5188 Y

| S/N                     | NATURE OF JOBS                                                                                                                                                               | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|----------------------------|
| 6                       | TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.                                                                      | S/N \$ 350.00     | /                          |
| 7                       | TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR.                                    | S/N \$ 280.00     | /                          |
| 8                       | TO REMOVE AND RENEW LHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME.                                                                                                            | S/N \$ 2,400.00   | ?                          |
| 9                       | TO SETUP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.                                                                                                                | S/N \$ 2,400.00   | ?                          |
| 10                      | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. | S/N \$ 1,400.00   | / (photo)                  |
| SUBTOTAL LABOUR CHARGES |                                                                                                                                                                              | : \$ 6,830.00     |                            |



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFV 5188 Y

| S/N                  | NATURE OF JOBS                                                                                                                                                                                                                                                   | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS               |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|------------------------------------------|
| 11                   | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT DRY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.                                                                                                         | S/N \$ 1,400.00   | / (photo)                                |
| 12                   | TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER, LHS REAR OUTER AND INNER WHEEL HOUSING AND LHS REAR INNER SIDE PANEL. TO REPAIR LHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | S/N \$ 10,000.00  | 3500<br>6 Lyr f. Rear f. fender<br>1 d.j |
| 13                   | TO RESPRAY REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR, TWO DOOR HANDLES, LHS WING MIRROR COVER, LHS REAR INNER SIDE PANEL, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE, REAR END PANELLING.                                                       | \$ 8,000.00       | 357 3675<br>6.5 x 550 + 100              |
| 14                   | TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.                                                                                                                                                                                                                     | S/N \$ 280.00     | X                                        |
| 15                   | TO RENEW LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.                                                                                                                                                                                          | S/N \$ 520.00     | 280                                      |
| 16                   | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.                                                                                                                                                                                                                          | S/N \$ 384.00     | /                                        |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                                                                                                  | : \$ 29,774.00    |                                          |



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 5188 Y

| S/N                          | PARTS DESCRIPTION                          | QTY | DAMAGED PARTS & PRICES |                  | REMARKS |
|------------------------------|--------------------------------------------|-----|------------------------|------------------|---------|
|                              |                                            |     | S/NETT                 |                  |         |
| 1                            | REAR BUMPER / (RM (phib))                  | 1   | \$                     | 2,609.00         |         |
| 2                            | REAR BUMPER FIXING PARTS X                 | 1   | \$                     | 480.00           |         |
| 3                            | REAR BUMPER GUIDE SECTION - LH ?           | 1   | \$                     | 49.00            |         |
| 4                            | REAR FENDER SIDE PANEL - LH ? / ON         | 1   | \$                     | 4,357.00         |         |
| 5                            | REAR RIVETTED CAP NUT / MC                 | 2   | \$                     | 7.00             |         |
| 6                            | REAR GROMMET / MC                          | 1   | \$                     | 2.00             |         |
| 7                            | REAR BLIND RIVET STUD / MC                 | 1   | \$                     | 10.00            |         |
| 8                            | REAR WINDOW NOT PRETREATED (MC glass) / MC | 1   | \$                     | 1,287.00         |         |
| 9                            | REAR SIDE WINDOW NOT PRETREATED- LH / MC   | 1   | \$                     | 685.00           |         |
| 10                           | PRIMER / MC                                | 2   | \$                     | 44.00            |         |
| 11                           | REAR WHEEL HOUSING - LH OUTER ?            | 1   | \$                     | 687.00           |         |
| 12                           | REAR WHEEL HOUSING INNER PART - LH ?       | 1   | \$                     | 1,338.00         |         |
| 13                           | REAR REINFORCEMENT C-PILLAR - LH LOWER ?   | 1   | \$                     | 220.00           |         |
| 14                           | REAR CONNECTING PLATE - LH ?               | 1   | \$                     | 218.00           |         |
| 15                           | REAR THREADED PLATE ?                      | 1   | \$                     | 11.00            |         |
| 16                           | REAR NOISE INSULATION PLATE - LH ?         | 2   | \$                     | 12.00            |         |
| 17                           | REAR VENT TRIM ?                           | 1   | \$                     | 75.00            |         |
| 18                           | REAR WHEEL HOUSING LINER - LH / (RM        | 1   | \$                     | 260.00           |         |
| 19                           | REAR DOOR - LH / ON                        | 1   | \$                     | 3,431.00         |         |
| 20                           | REAR OUTER DOOR SEAL - LH / MC             | 1   | \$                     | 229.00           |         |
| <b>SUB TOTAL SPARE PARTS</b> |                                            | :   | \$                     | <b>16,011.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 5188 Y

| S/N                          | PARTS DESCRIPTION                          | QTY | DAMAGED PARTS & PRICES |                 | REMARKS |
|------------------------------|--------------------------------------------|-----|------------------------|-----------------|---------|
|                              |                                            |     | S/NETT                 |                 |         |
| 21                           | BONDING AGENT / ne                         | 1   | \$                     | 51.00           |         |
| 22                           | CLEANING SOLUTION ne                       | 1   | \$                     | 74.00           |         |
| 23                           | APPLICATOR ne                              | 1   | \$                     | 8.00            |         |
| 24                           | REAR SEALING STRIP ?                       | 1   | \$                     | 19.00           |         |
| 25                           | REAR DOOR ATTACHMENT PARTS X               | 1   | \$                     | 943.00          |         |
| 26                           | REAR DOOR CATCH - LH ?                     | 1   | \$                     | 134.00          |         |
| 27                           | REAR OVAL HEXAGON SOCKET HEAD BOLT p. ?    | 2   | \$                     | 3.00            |         |
| 28                           | REAR INNER DOOR SEAL - LH X                | 1   | \$                     | 247.00          |         |
| 29                           | REAR DOOR TRIM PLATE HANDLE - LH / MIS     | 1   | \$                     | 98.00           |         |
| 30                           | REAR HOUSING - LH / ne                     | 1   | \$                     | 9.00            |         |
| 31                           | REAR TRANSPARENT COVER - LH / ne           | 1   | \$                     | 7.00            |         |
| 32                           | REAR SENSOR DOOR HANDLE - LH / MIS         | 1   | \$                     | 255.00          |         |
| 33                           | REAR EXTERIOR DOOR HANDLE / ne             | 1   | \$                     | 47.00           |         |
| 34                           | REAR & FRONT UNDERLAY - LH / ne            | 2   | \$                     | 8.00            |         |
| 35                           | REAR MOUNTING BAR - LH / BR (p/m)          | 1   |                        | TBC             |         |
| 36                           | REAR DOOR LOCK - LH ?                      | 1   | \$                     | 630.00          |         |
| 37                           | REAR STRIKER X                             | 1   | \$                     | 77.00           |         |
| 38                           | REAR DOOR TRIM LEATHERETTE - LH ?          | 1   | \$                     | 1,991.00        |         |
| 39                           | REAR WINDOW REGULATOR WITHOUT MOTOR - LH ? | 1   | \$                     | 305.00          |         |
| 40                           | REAR WINDOW REGULATOR MOTOR - LH ?         | 1   | \$                     | 371.00          |         |
| <b>SUB TOTAL SPARE PARTS</b> |                                            | :   | \$                     | <b>5,277.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5FV 5188 Y

|                       |                                                 |     | DAMAGED PARTS & PRICES |             |
|-----------------------|-------------------------------------------------|-----|------------------------|-------------|
| S/N                   | PARTS DESCRIPTION                               | QTY | S/NETT                 | REMARKS     |
| 41                    | REAR DOOR CONTROL UNIT ?                        | 1   | \$                     | 840.00      |
| 42                    | REAR TRIM FOR PILLAR C - LH / CM                | 1   | \$                     | 159.00      |
| 43                    | REAR TRIM FOR PILLAR B - LH / CM                | 1   | \$                     | 167.00      |
| 44                    | REAR SIDE WINDOW GUIDE RAIL - LH ?              | 1   | \$                     | 79.00       |
| 45                    | REAR WINDOW GUIDE - LH / CM                     | 1   | \$                     | 501.00      |
| 46                    | REAR WINDOW GUIDE TRIM STRIP ?                  | 1   | \$                     | 265.00      |
| 47                    | REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH / BT | 1   | \$                     | 410.00      |
| 48                    | REAR DOOR WINDOW - LH ?                         | 1   | \$                     | 322.00      |
| 49                    | REAR WIRING SET FOR DOOR - LH ?                 | 1   | \$                     | 414.00      |
| 50                    | REAR DOOR WIRING HARNESS TRIM PANEL ?           | 1   | \$                     | 328.00      |
| 51                    | REAR TRANSPARENT COVER - LH X                   | 1   | \$                     | 7.00        |
| 52                    | REAR SENSOR DOOR HANDLE - LH X                  | 1   | \$                     | 255.00      |
| 53                    | REAR EXTERIOR DOOR HANDLE X R                   | 1   | \$                     | 47.00       |
| 54                    | REAR UNDERLAY - LH X                            | 2   | \$                     | 8.00        |
| 55                    | REAR MIRROR CAP - LH X                          | 1   | \$                     | 308.00      |
| 56                    | REAR MIRROR GLASS WITH BEAM PLATE - LH X        | 1   | \$                     | 1,298.00    |
| 57                    | REAR TRIM FOR PILLAR B - LH / CM                | 1   | \$                     | 256.00      |
| 58                    | REAR TRIM STRIP FOR WINDOW GUIDE                | 1   | \$ ?                   | 287.00      |
| 59                    | REAR WINDOW GUIDE - LH / CM                     | 1   | \$                     | 501.00      |
| 60                    | REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH X    | 1   | \$                     | 344.00      |
| SUB TOTAL SPARE PARTS |                                                 |     | :                      | \$ 6,796.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 5188 Y

| S/N                  | PARTS DESCRIPTION                 | QTY | DAMAGED PARTS & PRICES |          | REMARKS   |
|----------------------|-----------------------------------|-----|------------------------|----------|-----------|
|                      |                                   |     | S/NETT                 |          |           |
| 61                   | REAR CORNER TRIM - LH X           | 1   | \$                     | 51.00    |           |
| 62                   | REAR FRONT DOOR WINDOW - LH / MY  | 1   | \$                     | 322.00   |           |
| 63                   | RUBBER VALVE ?                    | 1   | \$                     | 4.00     |           |
| 64                   | REAR SUPPORT FRAME ?              | 1   | \$                     | 3,643.00 |           |
| 65                   | REAR WISHBONE ALUMINIUM - LOWER ? | 1   | \$                     | 963.00   |           |
| 66                   | REAR WISHBONE - LH UPPER ?        | 1   | \$                     | 624.00   |           |
| 67                   | REAR FRONT WISHBONE - LH ?        | 1   | \$                     | 137.00   |           |
| 68                   | REAR STEEL WISHBONE - LH ?        | 1   | \$                     | 501.00   |           |
| 69                   | REAR TRACK ROD - LH ?             | 1   | \$                     | 188.00   |           |
| 70                   | REAR WHEEL BEARING HOUSING - LH ? | 1   | \$                     | 1,097.00 |           |
| 71                   | REAR WHEELHUB WITH BEARING ?      | 1   | \$                     | 723.00   |           |
| 72                   | REAR STONE CHIP GUARD ?           | 1   | \$                     | 49.00    |           |
| 73                   | REAR GAS SHOCK ABSORBER ?         | 1   | \$                     | 332.00   |           |
| 74                   | REAR COUPLING ROD ?               | 1   | \$                     | 94.00    |           |
| 75                   | ANTI-ROLL BAR ?                   | 1   | \$                     | 456.00   |           |
| 76                   | REAR LEVEL SENSOR - LH ?          | 1   | \$                     | 363.00   |           |
| 77                   | REAR WHEEL HOUSING TRIM - LH ?    | 1   | \$                     | 166.00   |           |
| 78                   | REAR B-PILLAR TRIM - LH LOWER ?   | 1   | \$                     | 171.00   |           |
| TOTAL SPARE PARTS    |                                   |     | :                      | \$       | 37,968.00 |
| TOTAL LABOUR CHARGES |                                   |     | :                      | \$       | 29,774.00 |
| GRAND TOTAL          |                                   |     | :                      | \$       | 67,742.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Stew (LKK)  
18/7/22, 2.9P

OD M AL  
Excess - ?  
14 Lp  
P/P  
L 1.27

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

( Request CI )

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: