

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0591/2022/EQ
DATE : 16-Jul-22
WIP : 33072

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/07/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Steve
22 days exclude 4 Sundays
Johnny Boo 27 Sep 22

OWNER'S NAME : MR LEE CHOON KIAT
ADDRESS : BLK 427 SERANGOON CENTRAL
#05-300
SINGAPORE 550427
TELEPHONE : HP +65 9616 1026
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800039936-04
VEHICLE NO : **SFV 5188 Y**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 23/4/2018
ENGINE NO : CVK 057988
CHASSIS NO : WAUZZZF44JA139441
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Jul-22
PLACE OF ACCIDENT : DEFU LANE 10

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFV 5188 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	600.00	\$ 600.00
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$	200.00	\$ 150.00
4	TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES.	S/N \$	400.00	\$ 400.00
5	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$	800.00	
SUBTOTAL LABOUR CHARGES		: \$	2,360.00	\$ 1,510.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFV 5188 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 1,510.00
6	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	\$ 350.00
7	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR.	S/N \$	280.00	\$ 280.00
8	TO REMOVE AND RENEW LHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00	
9	TO SETUP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	\$ 1,400.00
SUBTOTAL LABOUR CHARGES		:	\$ 6,830.00	\$ 3,540.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFV 5188 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 3,540.00
11	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT DRY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	\$ 1,400.00
12	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER, LHS REAR OUTER AND INNER WHEEL HOUSING AND LHS REAR INNER SIDE PANEL. TO REPAIR LHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$	10,000.00	\$ 5,000.00
13	TO RESPRAY REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR, TWO DOOR HANDLES, LHS WING MIRROR COVER, LHS REAR INNER SIDE PANEL, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE, REAR END PANELLING.	\$	8,000.00	\$ 4,225.00
14	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	
15	TO RENEW LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	\$ 280.00
16	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 29,774.00	\$ 14,829.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 5188 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,609.00	\$	2,087.20
2	REAR BUMPER FIXING PARTS	1	\$ 480.00		
3	REAR BUMPER GUIDE SECTION - LH	1	\$ 49.00		
4	REAR FENDER SIDE PANEL - LH	1	\$ 4,357.00	\$	3,485.60
5	REAR RIVETTED CAP NUT	2	\$ 7.00	\$	5.60
6	REAR GROMMET	1	\$ 2.00	\$	1.52
7	REAR BLIND RIVET STUD	1	\$ 10.00	\$	7.84
8	REAR WINDOW NOT PRETREATED	1	\$ 1,287.00	\$	1,029.60
9	REAR SIDE WINDOW NOT PRETREATED- LH	1	\$ 685.00	\$	548.00
10	PRIMER	2	\$ 44.00	\$	34.72
11	REAR WHEEL HOUSING - LH OUTER	1	\$ 687.00	\$	549.60
12	REAR WHEEL HOUSING INNER PART - LH	1	\$ 1,338.00		
13	REAR REINFORCEMENT C-PILLAR - LH LOWER	1	\$ 220.00	\$	175.60
14	REAR CONNECTING PLATE - LH	1	\$ 218.00		
15	REAR THREADED PLATE	1	\$ 11.00		
16	REAR NOISE INSULATION PLATE - LH	2	\$ 12.00		
17	REAR VENT TRIM	1	\$ 75.00		
18	REAR WHEEL HOUSING LINER - LH	1	\$ 260.00	\$	208.00
19	REAR DOOR - LH	1	\$ 3,431.00	\$	2,744.80
20	REAR OUTER DOOR SEAL - LH	1	\$ 229.00	\$	182.80
SUB TOTAL SPARE PARTS		:	\$ 16,011.00	\$	11,060.88

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 5188 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	11,060.88
21	BONDING AGENT	1	\$	51.00	\$ 40.48
22	CLEANING SOLUTION	1	\$	74.00	\$ 58.80
23	APPLICATOR	1	\$	8.00	\$ 6.40
24	REAR SEALING STRIP	1	\$	19.00	
25	REAR DOOR ATTACHMENT PARTS	1	\$	943.00	
26	REAR DOOR CATCH - LH	1	\$	134.00	\$ 106.80
27	REAR OVAL HEXAGON SOCKET HEAD BOLT	2	\$	3.00	\$ 2.24
28	REAR INNER DOOR SEAL - LH	1	\$	247.00	
29	REAR DOOR TRIM PLATE HANDLE - LH	1	\$	98.00	\$ 77.92
30	REAR HOUSING - LH	1	\$	9.00	\$ 6.88
31	REAR TRANSPARENT COVER - LH	1	\$	7.00	\$ 5.36
32	REAR SENSOR DOOR HANDLE - LH	1	\$	255.00	\$ 203.60
33	REAR EXTERIOR DOOR HANDLE	1	\$	47.00	\$ 37.12
34	REAR & FRONT UNDERLAY - LH	2	\$	8.00	\$ 6.40
35	REAR MOUNTING BAR - LH	1		TBC	\$ 146.00
36	REAR DOOR LOCK - LH	1	\$	630.00	\$ 503.60
37	REAR STRIKER	1	\$	77.00	
38	REAR DOOR TRIM LEATHERETTE - LH	1	\$	1,991.00	
39	REAR WINDOW REGULATOR WITHOUT MOTOR - LH	1	\$	305.00	
40	REAR WINDOW REGULATOR MOTOR - LH	1	\$	371.00	
SUB TOTAL SPARE PARTS		:	\$	5,277.00	\$ 12,262.48

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 5188 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>12,262.48</i>
41	REAR DOOR CONTROL UNIT	1	\$ 840.00		
42	REAR TRIM FOR PILLAR C - LH	1	\$ 159.00	<i>\$</i>	<i>127.20</i>
43	REAR TRIM FOR PILLAR B - LH	1	\$ 167.00	<i>\$</i>	<i>133.60</i>
44	REAR SIDE WINDOW GUIDE RAIL - LH	1	\$ 79.00		
45	REAR WINDOW GUIDE - LH	1	\$ 501.00	<i>\$</i>	<i>400.80</i>
46	REAR WINDOW GUIDE TRIM STRIP	1	\$ 265.00		
47	REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH	1	\$ 410.00	<i>\$</i>	<i>327.60</i>
48	REAR DOOR WINDOW - LH	1	\$ 322.00		
49	REAR WIRING SET FOR DOOR - LH	1	\$ 414.00	<i>\$</i>	<i>331.20</i>
50	REAR DOOR WIRING HARNESS TRIM PANEL	1	\$ 328.00	<i>\$</i>	<i>262.40</i>
51	REAR TRANSPARENT COVER - LH	1	\$ 7.00		
52	REAR SENSOR DOOR HANDLE - LH	1	\$ 255.00		
53	REAR EXTERIOR DOOR HANDLE	1	\$ 47.00		
54	REAR UNDERLAY - LH	2	\$ 8.00		
55	REAR MIRROR CAP - LH	1	\$ 308.00		
56	REAR MIRROR GLASS WITH BEAM PLATE - LH	1	\$ 1,298.00		
57	REAR TRIM FOR PILLAR B - LH	1	\$ 256.00	<i>\$</i>	<i>204.40</i>
58	REAR TRIM STRIP FOR WINDOW GUIDE	1	\$ 287.00		
59	REAR WINDOW GUIDE - LH	1	\$ 501.00	<i>\$</i>	<i>400.80</i>
60	REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH	1	\$ 344.00		
SUB TOTAL SPARE PARTS		:	\$ 6,796.00	<i>\$</i>	<i>14,450.48</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 5188 Y

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		\$	14,450.48
61	REAR CORNER TRIM - LH	1	\$	51.00	
62	REAR FRONT DOOR WINDOW - LH	1	\$	322.00	\$ 257.20
63	RUBBER VALVE	1	\$	4.00	
64	REAR SUPPORT FRAME	1	\$	3,643.00	
65	REAR WISHBONE ALUMINIUM - LOWER	1	\$	963.00	
66	REAR WISHBONE - LH UPPER	1	\$	624.00	
67	REAR FRONT WISHBONE - LH	1	\$	137.00	
68	REAR STEEL WISHBONE - LH	1	\$	501.00	
69	REAR TRACK ROD - LH	1	\$	188.00	
70	REAR WHEEL BEARING HOUSING - LH	1	\$	1,097.00	
71	REAR WHEELHUB WITH BEARING	1	\$	723.00	
72	REAR STONE CHIP GUARD	1	\$	49.00	
73	REAR GAS SHOCK ABSORBER	1	\$	332.00	
74	REAR COUPLING ROD	1	\$	94.00	
75	ANTI-ROLL BAR	1	\$	456.00	
76	REAR LEVEL SENSOR - LH	1	\$	363.00	
77	REAR WHEEL HOUSING TRIM - LH	1	\$	166.00	
78	ADDED PARTS - SEE ATTACHED		\$	81.00	\$ 64.24
79	ADDED PARTS - SEE ATTACHED		\$	1,580.00	\$ 1,113.76
81	REAR B-PILLAR TRIM - LH LOWER	1	\$	171.00	
TOTAL SPARE PARTS		:	\$	39,629.00	\$ 15,885.68
TOTAL LABOUR CHARGES		:	\$	29,774.00	\$ 14,829.00
GRAND TOTAL		:	\$	69,403.00	\$ 30,714.68

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-08/09/22



55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0591/2022/TF 4-Aug-22 Tony 1 of 1 SFV 5188 Y AUDI A4 SEDAN 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	REAR DOOR HANDLE LIGHT - LH	\$ 81.00	\$ 64.24	
	GRAND TOTAL	\$ 81.00	\$ 64.24	

For Premium Automobiles Pte Ltd

Authorised Signature



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0591/2022/TF 9-Sep-22 GLORY 1 of 1 SFV 5188 Y AUDI A4 SEDAN 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	SUNDRIES	\$ 500.00	\$	33.76
2	ACRYLIC SEALANT	\$ 180.00	\$	180.00
3	CAVITY WAX	\$ 140.00	\$	140.00
4	STONE CHIP	\$ 180.00	\$	180.00
5	METAL FILLER POWDER	\$ 280.00	\$	280.00
6	REAR WINDSCREEN SEALANT	\$ 200.00	\$	200.00
7	1/4 GLASS SEALANT	\$ 100.00	\$	100.00
GRAND TOTAL		\$ 1,580.00	\$	1,113.76

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT