

REF:

ASSIGNMENT

Veh No: SCJ937. Yr Regn: 2021 / Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 C.C 1984

Colour: Green A/C: Insured / Std / Ni / NA

Sp. Reading 12788 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZF28MN098212

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/40R20.

R: 255/40R20.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 00 mm

D.O.A. D.O.I. 21/07/22

Survey held at Idemium.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	T P ALG.
	MV :
	PV :
	Nett:

☐: Prel. Report

☐ : Final Report

Resurvey No. of Trip:

☐ : Site Insp (\$

☐ Interview (\$

Tech. Invs (3)

Transportation:

Photos

2. Officers

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0606/2022/EQ
DATE : 19-Jul-22
WIP : 33536

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 21/7/2022.

YOUR INSURED VEH NO : SLD 8865 E

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

OWNER'S NAME : MR. LEE MENG KEE
ADDRESS : BLK 228A ANG MO KIO ST 23
#24-33
SINGAPORE 561228
TELEPHONE : HP +65 83882000
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210104914
VEHICLE NO : **SCJ 93 T**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 9/9/2021
ENGINE NO : DKY 015967
CHASSIS NO : WAUZZZF28MN098212
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jul-22
PLACE OF ACCIDENT : ALONG ANG MO KIO AVE 2
TOWARDS ANG MO KIO AVE 1

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCJ 93 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	X.
2	TO REMOVE AND TRANSFER RHS FRONT DOOR 'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	280. ✓
3	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. TO REPAIR RHS REAR DOOR AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,000.00	1000. 1,500.00
4	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, DOOR HINGES, RHS WING MIRROR COVER, DOOR HANDLE, RHS REAR DOOR AND RHS REAR FENDER.	\$	4,500.00	2350 550 x 4 = 2200 Mirror = 150 2350 ✓
5	TO RENEW RHS FRONT RIM AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	560.00	280 ✓
6	TO CARRY OUT CALIBRATION FOR RHS WING MIRROR 360 CAMERA.	S/N \$	480.00	✓ ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$ 10,612.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCJ 93 T

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT FENDER - RH <i>Distorted</i>	1	\$ 1,649.00	✓	1,319.20
2	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 44.00	+	
3	FRONT FENDER BRACE - RH <i>new</i>	1	\$ 137.00	+	
4	FRONT FENDER BRACKET - RH UPPER ?	1	\$ 49.00	?	X NN
5	FRONT FENDER CLOSING ELEMENT - RH ?	1	\$ 60.00	?	X NN
6	FRONT WHEEL HOUSING LINER - RH <i>new</i>	1	\$ 299.00	+	
7	FRONT FENDER STONE CHIP GUARD - RH <i>ut</i>	1	\$ 57.00	✓	45.28
8	FRONT FENDER BRACKET TRIM - RH ?	1	\$ 45.00	?	X NN
9	FRONT DOOR - RH <i>Defed</i>	1	\$ 4,489.00	✓	3,591.20
10	FRONT OUTER DOOR SEAL - RH <i>new</i>	1	\$ 191.00	✓	152.80
11	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 379.00	+	
12	FRONT DOOR CATCH - RH ?	1	\$ 134.00	?	X NN
13	FRONT EXTERIOR MIRROR MOUNTING - RH <i>new</i>	1	\$ 3,069.00	+	
14	FRONT MIRROR CAP - RH <i>Repair</i>	1	\$ 348.00	+	
15	FRONT WINDOW SLOT SEAL TRIM STRIP - RH OUTER <i>new</i>	1	\$ 224.00	+	
16	FRONT DOOR HINGE - RH UPPER / LOWER ?	2	TBC	?	X NN
17	SUNDRIES ?	\$	500.00	?	X NN
18	RHS FRONT RIM <i>ut</i>	S/N	TBC	✓	159.92 X
19	RHS REAR RIM <i>Repair</i>	S/N	TBC	X	
TOTAL SPARE PARTS		:	\$	11,674.00	
TOTAL LABOUR CHARGES		:	\$	10,612.00	
GRAND TOTAL		:	\$	22,286.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Ling.
SURVEYED DATE : 21/07/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorized, 07 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Cecilia.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/0606/2022/EQ

23-Aug-22

CHANG

1 of 1

SCJ 93 T

AUDI A6 DESIGN 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND REINSTALL RHS SILL PANEL TRIM.	\$ 1,200.00	1,200.00 500
2	TO RESPRAY RHS SILL PANEL TRIM.	\$ 1,200.00	2,400.00 550
<u>Parts</u>			
1	1 SET ATTACHMENT PARTS <i>free</i>	\$ 136.00	✓ 108.80
2	1 SET ADHESIVE TAPES	\$ 64.00	✓ 51.12
GRAND TOTAL		\$ 2,600.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
AS

Add 1 Day for the removal and spray painting for sill panel trim.